

MS Car Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

Tel: 6385-1838 / 9725 4442 Fax: 6386-1838 Email: motorstopoffice@gmail.com / motorstopservices@gmail.com/ msgroupoffice@gmail.com

SJE : _____

Vehicle Nos : FBP 2763K

Date of Survey : _____

Model : Yamaha Aerox S 155

Contacts : _____

Year : _____

**** AGREED COR and Days with SJE ****

Amount : _____

Nos.	PARTS	QTY	UNIT S\$	Total S\$
1	HEARLAMP	1	\$ 385.00	\$ 385.00
2	HEARLAMP COVER	1	\$ 145.00	\$ 45.00
3	HEARLIMP BRACKET	1	\$ 120.00	\$ 120.00
4	FENDER FRONT	1	\$ 175.40	\$ 175.40
5	TAIL SIDE COVER R/H	2	\$ 136.70	\$ 273.40
6	SHOCK ABSORBER OHLINS	1	\$ 1,060.00	\$ 1,060.00
7	REAR ARM BRACKET	1	\$ 238.60	\$ 238.60
8	REAR ARM BRACKET BEARING	1	\$ 65.00	\$ 65.00
9	FRONT FOCK	1	\$ 718.10	\$ 718.10
10	FRONT FOCK BRACKET	1	\$ 118.10	\$ 218.10
11	UNDER BRACKET	1	\$ 284.80	\$ 284.80
12	STEERING BEARING	1	\$ 76.00	\$ 76.00
13	REAR FENDER	1	\$ 97.20	\$ 97.20
14	HANDLE BAR	1	\$ 167.50	\$ 167.50
15	HANDLE BAR END MIRROR R//L	2	\$ 95.00	\$ 190.00
16	BALANCE	1	\$ 83.50	\$ 83.50
17	BEAKE LEVER	1	\$ 86.30	\$ 86.30
18	FOOTREST LOWER SIDE COVER R/L	2	\$ 72.60	\$ 145.20
19	BODY, COWLING R/L	2	\$ 127.90	\$ 255.80
20	EMBLEM YAMAHA LIGHT	1	\$ 35.00	\$ 35.00
21	EMBLEM YAMAHA LEFT	1	\$ 35.00	\$ 35.00
22	NUMBER PLATE	1	\$ 25.00	\$ 25.00
23	RADIATOR PIPE	1	\$ 75.60	\$ 75.60
24	MAIN STAND	1	\$ 164.00	\$ 164.00
25	FRONT RIM	1	\$ 188.50	\$ 188.50
26	FRONT TYPE	1	\$ 152.40	\$ 152.40
27	ENGINE COVER R/H	1	\$ 183.00	\$ 183.00
28	FRONT BREAK DISE	1	\$ 165.60	\$ 165.60
29	FOOTREST COVER R/L	2	\$ 95.00	\$ 190.00
30	FRONT COWLING	1	\$ 135.30	\$ 135.30
31	SIDER FARLING R/L	2	\$ 237.20	\$ 474.40
32	SIDER REAR FARLING R/L	2	\$ 153.70	\$ 307.40
33	EXHAUST ASSY	1	\$ 782.50	\$ 782.20
34	EXHAUST COVER	1	\$ 144.60	\$ 124.60
35	EXHAUST PROTERTOR	1	\$ 73.10	\$ 53.10
		Total Price		\$ 7,776.00
		Less 10%		\$ 777.60
		Sub Total Price		\$ 6,998.40

Nos.	Claims Details : Labour and Spray Painting	Total S\$
1	To Replace Accident Affected Areas	\$ 500.00
2	To Putty And Spary Paint Affected Areas	\$ 500.00
3	To Check Wheel Alignment	\$ 50.00
4	Front Fork Oil	\$ 30.00
5	IU	\$ 180.00
6	BOX	\$320
Total		\$ 1,580.00

PARTS TOTAL \$ 6,998.40
LABOUR TOTAL \$ 1,580.00
OVERALL TOTAL \$ 8,578.40

NAME OF SURVEYOR :

REMARKS :

BR
CUT
BT
CUT
X SVC
X SVC
X SVC
BT
X SVC
BT
nec
BT
X HF
40/ CUT
25/ CUT
CUT
CUT
nec
nec
nec
X SVC
X SVC
CUT
X SVC
CUT
X SVC
CUT
X SVC
CUT
180/ BR
CUT
X SVC
X SVC
CUT
CUT
3587.3
- 10%
3228.57

300
300
30
20
150
800

= 4028.57
L/S - 3222.85
= 3200

4 days

VEHICLE TO BE SURVEYED: FBP 2763K

China Taip

LKK

ACCIDENT DATE : 13/5/19 - 07:30

ACCIDENT INVOLVING : FBP 2763K & YL 6254K

Mark

ACKNOWLEDGEMENT OF SURVEY(S)

** PRE-REPAIR INSPECTION

* GIA report

Name of Surveyor: Steve HP / Email: Steve.chen@lkkarb.com
83228813


Date of Survey : 16/5/19 Time: 3.00pm

Surveyor Signature : 

** Re-Survey / Question Mark Items

Name of Surveyor: Tanghh HP / Email: _____

Date of Survey : 10/6/19 Time: 550pm

Surveyor Signature : 

** AFTER - REPAIR INSPECTION

Name of Surveyor: Adrain HP / Email: _____

Date of Survey : 28/7/19 Time: 4pm ?

Surveyor Signature : _____