

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

Vehicle No: SKU6099K

Model: Toyota Altis

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Rear bumper	\$ 482.00 800.00 CUT ✓
1	Rear bumper bracket (retainer)	\$ 158.00 200.00 NEC ✓
1	Rear bumper boot panel	\$ 1,200.00 ND X
1	Rear R/H fender	\$ 500.00 CUT X R
1	Rear R/H tyre mudflap	\$ 56.00 250.00 CUT ✓
1	Rear R/H rims	\$ 300.00 600.00 CUT ✓

996.00

@ 25%

249.00

747.00

\$ 3,550.00

c/f: \$

\$ 3,550.00

Special Nett Items

AMT SS

1	Rear bumper Panel clip	\$ 30.00	150.00
		\$ 30.00	150.00

S/N. Labour Charges

1	Remove and refit Panels	\$	600.00	400.00
2	Apply tuff kote	\$	300.00	NNX
3	Remove, refit and replaced damage and check up rear electrical wiring	\$	150.00	30.00 ✓
4	Remove and refit inner garnishes trim to assist repair	\$	200.00	NNX
5	To apply undercoating on replaced panel	\$	120.00	NNX
6	To Respray Painting	\$	800.00	400.00
		\$	2,170.00	830.00
	GRAND TOTAL	\$	<u>5,870.00</u>	

PARTS 747.00
 S/N 30.00
 LABOUR 830.00
1,607.00

@ 20% 321.40
1285.60

4/5 1250/2

Survey:

21/1/2021 1st 2nd 3rd

(delete accordingly)

Surveyor Details:

22/1/2021

(Name)

TCM Lin

(Contact)

(Email)

(Signature)

Lin

(Date/Time)

1300h

Lump sum repair

Repair day 4

TCM Lin

22/1/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: