



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2102593
3 ANSON ROAD #16-00	INV Date	14/04/2021
SPRINGLEAF TOWER	Reference	CC6/CTI21001036/Ara3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SJV 4928M
Insured Veh.	GBD 2406E
Claim No.	SNM21D200372/LKKDS
Policy No.	DMCVSNW0057722002
Accident Date	20/01/2021
Inspection Date	21/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21001036/Ara3q2 Date: 14/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 2406E	Veh. Inspected	SJV 4928M
Policy No.	DMCVSNW0057722002	Coverage (\$)	0.00
Claim No.	SNM21D200372/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	21/01/2021
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO FORTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFU411LA5137627	Colour	BRONZE
Odometer	408027 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/01/2021	Inspection Date	21/01/2021
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 4928M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (N)	TORN	601.00	601.00
10	REAR BUMPER CLIP @\$6.50 (N)	NECESSARY	65.00	30.00
1	REAR R/H BUMPER SIDE RETAINER (N)	CRACKED	25.00	25.00
1	REAR R/H TAILLAMP (N)	NOT NECESSARY	295.00	-
1	REAR R/H FENDER (N)	TO REPAIR SEE LABOUR	1,133.00	-
1	REAR R/H FENDER COWLING (N)	NOT NECESSARY	135.00	-
10	REAR R/H FENDER COWLING CLIP @\$6.50 (N)	NOT NECESSARY	65.00	-
1	REAR R/H DOOR (N)	DISTORTED	1,021.00	1,021.00
2	REAR R/H DOOR HINGE @\$65.00 (N)	NOT NECESSARY	130.00	-
2	REAR R/H DOOR FRAME STICKER @\$42.00 (N)	NECESSARY	84.00	84.00
1	REAR R/H DOOR OUTER HANDLE (N)	CUT	196.00	196.00
1	REAR R/H DOOR INNER LOCK (N)	DAMAGED	238.00	238.00
1	REAR R/H DOOR INNER TRIM BOARD (N)	CRACKED	856.00	495.00
8	REAR R/H DOOR INNER TRIM BOARD CLIP @\$6.50 (N)	NECESSARY	52.00	30.00
1	REAR R/H DOOR WEATHERSTRIP (N)	NOT NECESSARY	290.00	-
1	REAR R/H DOOR WINDOW REGULATOR MOTOR ASSY (N)	DAMAGED	684.00	339.00
1	REAR R/H DOOR CENTER MOULDING (N)	NOT NECESSARY	210.00	-
1	REAR R/H SHOCK ABSORBER (N)	BENT	290.00	290.00
1	REAR R/H AXLE BEARING (N)	DAMAGED	398.00	398.00
1	REAR AXLE (N)	BENT	1,373.00	1,373.00
	LESS 10% DISCOUNT		-	-512.00
			8,141.00	4,608.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR R/H TYRE (SN)	CUT	350.00	200.00
1	REAR R/H RIM (SN)	CUT	800.00	500.00
			1,150.00	700.00
<u>LABOUR</u>				
	TO REMOVE & REFIT REAR CUSHION & TRIM BOARD .		280.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REAR R/H DOOR ,LOCK ,GLASS ,WEATHERSTRIP ,TRIM BOARD ,FRAME STICKER & WINDOW MOTOR REGULATOR .		350.00	80.00
	TO REMOVE & REFIT REAR AXLE ,BEARING & ABSORBER .		450.00	300.00
	TO REMOVE & REFIT REAR WINDSCREEN .	NOT NECESSARY	120.00	-
	GUM.	NOT NECESSARY	50.00	-
	TO CHECK WIRING .		150.00	30.00
	TUFF KOTE.		200.00	60.00
	TOWING FEE.	NOT NECESSARY	150.00	-
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR R/H FENDER .		1,800.00	600.00
	SPRAY PAINTING .		1,800.00	700.00
			5,350.00	1,830.00
GRAND TOTAL			14,641.00	7,138.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CC6/CT121001036/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 4928M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 4928M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 4928M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

