

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

20/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chim
Jashin

Accident date: 20/01/2020

Estimated repair cost for vehicle no: SJV4928M KIA CERATO EX FORTE 1.6L

CHASSIS: KNAFU411LA5137627

S/n	Qty	Items / Nett	U/price	Amount
1	1	Rear Bumper <i>torn</i>		\$601.00 ✓
2	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>
3	1	Rear R/H Bumper Side Retainer <i>could</i>		\$25.00 ✓
4	1	Rear R/H Taillamp <i>new</i>		\$295.00 ✗
5	1	Rear R/H Fender <i>Repair</i>		\$1,133.00 ✗
6	1	Rear R/H Fender Cowling <i>2nd</i>		\$135.00 ✗
7	10	Rear R/H Fender Cowling Clip <i>1st</i>	\$6.50	\$65.00 ✗
8	1	Rear R/H Door <i>Replaced</i>		\$1,021.00 ✓
9	2	Rear R/H Door Hinge <i>new</i>	\$65.00	\$130.00 ✗
10	2	Rear R/H Door Frame Sticker <i>new</i>	\$42.00	\$84.00 ✓
11	1	Rear R/H Door Outer Handle <i>cut</i>		\$196.00 ✓
12	1	Rear R/H Door Inner Lock <i>Damaged</i>		\$238.00 ✓
13	1	Rear R/H Door Inner Trim Board <i>could</i>		\$856.00 ✓ <i>495</i>
14	8	Rear R/H Door Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 <i>30</i>
15	1	Rear R/H Door Weatherstrip <i>new</i>		\$290.00 ✗
16	1	Rear R/H Door Window Regulator Motor Assy <i>2nd</i>		\$684.00 ✓ <i>339</i>
17	1	Rear R/H Door Center Moulding <i>new</i>		\$210.00 ✗
18	1	Rear R/H Tyre <i>cut</i>		\$350.00 <i>200(SN)</i>
19	1	Rear R/H Rim <i>cut</i>		\$800.00 <i>\$00(SN)</i>
20	1	Rear R/H Shock Absorber <i>Best</i>		\$290.00 ✓
21	1	Rear R/H Axle Bearing <i>Best</i>		\$398.00 ✓
22	1	Rear Axle <i>Best</i>		\$1,373.00 ✓

Subtotal :- \$9,291.00

S/D 20

H 608

S/N: 700

Labour charges

To remove & refit rear cushion & trim board	\$280.00	60
To remove & refit rear R/H door, lock, glass, weatherstrip, trim board, frame sticker & window motor regulator	\$350.00	80
To remove & refit rear axle, bearing & absorber	\$450.00	300
To remove & refit rear windscreen	\$120.00	X
Gum	\$50.00	X
To check wiring	\$150.00	30
Tuff kote	\$200.00	60
Towing Fee	1830	\$150.00 X
Panel beating	\$1,800.00	600
Spray painting	\$1,800.00	700

Subtotal :- \$5,350.00

Total:- \$14,641.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adria G
c/s 21/01/21

06 Days

total 7138

H/S: 5.7K

5.7K