



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/6133/9114/TP/10.20
Vehicle Number : YP 9114R

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		SPECIAL NETT ITEMS:-			
1	1 pc	rear box rh rear pillar	buckled	\$ 800.00	\$ 700 800.00
2	1 pc	rear box rh lower frame	buckled	\$ 1,100.00	\$ 600 1,100.00
				\$ 1,900.00	\$ 1,900.00
		LABOUR & OTHER CHARGES:-			
3		To remove and replace rear pillar and lower frame	<u>600</u>	\$ 1,600.00	\$ 500 1,200.00
4		To carry out electrical check		\$ 60.00	\$ xnn 50.00 x
5		To putty and spray-paint of affected areas		\$ 800.00	\$ 100 600.00
				\$ 2,460.00	\$ 1,850.00
					1300
					600
					<u>1900</u>
					20%
					1520
					<u>L/S - 1500</u>
					<u>4 DAYS</u>
Sub - Total				\$ 4,360.00	\$ 3,750.00