

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21001044/T1VF3E2
Date: 25/02/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SGJ8080E **Insured Vehicle No :** YQ1995L
Date of Loss: 20/01/2021 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGJ8080E**
Make & Model: NISSAN SERENA, 1.2 L HIGHWAY STAR PREMIUM E-POWER (A) Engine No: HR12114905K
Reg. Date: 30/11/2019 (Man. Year: 2019) Chassis No: JN1EBAC27Z0000217
Colour: White Odometer: 30792 km
Engine Capacity: 1198 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,280.72	5,231.60	49.12	0.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,938.00	1,078.00	860.00	44.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,218.72	6,309.60	909.12	12.59
+ GST 7.00/7.00% (S\$)	505.31	441.67	63.64	12.59
Nett Amount (S\$)	7,724.03	6,751.27	972.76	12.59

INSPECTION

Date of Assignment: 22/01/2021
Date Inspected: 22/01/2021 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$19.12 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2021)

Parts: M1-MPV NISSAN SERENA 1.2 L HIGHWAY STAR PREMIUM E-POWER (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGJ8080E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*CLIP RH RR COMB LAMP	Necessary	9.80 FN	*9.80 FN
2	2		*GROMET RH RR COMB LAMP	Necessary	9.80 FN	*9.80 FN
3	1		*RH RR COMBINATION LAMP	Cracked	560.30 FN	*560.30 FN
4	1		*EMBLEM-RR E POWER	Necessary	94.40 FN	*94.40 FN
5	1		*EMBLEM-REAR HIGHWAY STAR	Necessary	50.90 FN	*50.90 FN
6	1		*REAR EMBLEM NISSAN	Necessary	79.90 FN	*79.90 FN
7	1		*TAIL GATE CHROME MOULDING (SERENA)	Cracked	797.20 FN	*797.20 FN
8	1		*TOP BACK DOOR CHROME MOULDING	Cracked	797.20 FN	*797.20 FN
9	1		*RH BACK DOOR RUBBER	* Check	23.90 FN	*- FN
10	1		*REAR WINDSCREEN GLASS	Broken	4,015.00 FN	*4,015.00 FN
11	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
12	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	6,568.40	6,514.50
- Nett Item Discount on N Items 20.00/20.00% (S\$)	1,287.68	1,282.90
Total Parts (S\$)	5,280.72	5,231.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REPAIR TAIL GATE, RH RR CORNER PANEL AND REAR BUMPER	New	750.00	390.00
2	CHARGES TO SPRAY PAINTING SAME	New	750.00	250.00
3	RENEW RH RR TAIL LAMP	New	48.00	48.00
4	RENEW REAR WINDSCREEN GLASS	New	240.00	240.00
5	RENEW REAR WINDSCREEN GLASS SOLAR FILM	New	150.00	150.00
			Gross Labour Cost (\$\$)	1,938.00
				1,078.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >