

SERVE YOU MOTOR SERVICE
BLOCK 5033 ANG MO KIO IND. PARK 2 #01-265
SINGAPORE 569536
TEL. NO: 64815652 FAX: 64831654
REG. NO. 224630/00L
E-MAIL: serveyou5033@gmail.com

Our Ref: PC 3036 Y

Your Ref: GBH 4306 B

Date: 21/01/2021

M/s : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES NO. PC 3036 Y AND GBH 4306 B

ACCIDENT DATE: 20/01/2021 Along/At Bendemeer Road.

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

We have been authorized by the registered owner of Vehicle No. **PC 3036 Y** which was involved in the above mentioned accident.

We understand that Vehicle No. **GBH 4306 B** was insured by you.

Please arrange with your surveyor to conduct a pre-repair inspection on our customer's vehicle bearing registration **PC 3036 Y** at our workshop.

If we do not hear from you within 2 working days from the date of this notice, we have the owner's instruction to appoint an independent surveyor to survey and repair his vehicle, and also to claim for any additional loss of use arising from the date of this notification being issued to you.

Yours faithfully,

Elaine Chia (H/P: 92393188)
SERVE YOU MOTOR SERVICE

