

SERVE YOU MOTOR SERVICE

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
#01-265, SINGAPORE 569536

TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: elainesyms@gmail.com

*Not Authorised
11/12/2021 8:49:00pm
Pehng Ater Pehng*

INS: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

COMPANY: BUS TECH PTE LTD

Registration no. PC 3036 Y

Acc/date: 20/1/2021

Date: 21-Jan-21

TOYOTA / HIACE HIGH ROOF COMMUTER TURBO AUTO

Quotation No. : 202130362001

S/N	Qty	Particulars	Amount
-----	-----	-------------	--------

LIST ITEMS

1	1	Rear Tailgate Assy	R 2054.23 ✓
2	1	Rear Tailgate Inner Trim Board	Bu 428.25 ✓
6	1	Rear Tailgate inner lock	Tr 359.10 ✓
7	1	Rear Tailgate inner rubber	R 392.40 X
8	2	Rear Tailgate shock absorber (@ \$ 185 each)	d/s R 370.00 ✓
	1	Rear RH body inner pillar 642.80	R 750.00 ✓
9	1	Rear End Panel 581.45	R 654.00 ✓
10	1	Rear End Panel Inner Aluminium Trim	Tr 110.50 X
11	1	Rear bumper	Bu 372.70 ✓
12	1 set	Rear bumper bracket	R 138.00 ✓
13	1	Rear Fender Corner	R 198.10 ✓
14	1	Rear Tail Lamp 354.20	Bu 499.40 ✓
15	1	Rear RH Fender	Bu 1259.23 ✓
16	1 set	Rear bumper side retainer \$68 each	c/s R 136.00 ✓
17	1 set	Rear corner panel both side \$224 each	c/s R 448.00 ✓
18	1	Rear RH Corner Inner Panel Side Cover	R 450.00 ✓
19	1	Rear RH Inner Panel Corner Side Rubber board cover	d/s R 55.00 ✓
20	1	Front RH Door R X	
21	1	Front Bumper Assy 523.20	Net 557.00 ✓
22	1	Front Bumper Retainer	R 88.80 X
23	1	Front Lamp Garnish	R 110.40 X
24	1	Front Head Lamp	R 548.00 X
			9979.11
			-2494.78
			7484.33

SPECIAL NETT ITEMS

4pcs	Reverse sensor
1	School Bus Silhouette logo with lights
1	Tailgate emblem " 70Km/h "
1 set	Company logo sticker
1	Rear Emergency Sticker
1	Rear Tailgate Emblem
1	Rear Toyota Hiace Sticker
1	Rear number plate
2	Rear passenger seat support hole

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Lessee" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

R	300.00
Bu	480.00
R	150.00
R	50.00
(Bill)	500.00
R	30.00
R	38.00
R	84.00
R	50.00
R	90.00

1	Rear Windscreen Wiper		80.00 X
1	Rear Windscreen Motor		330.00 X
1 set	Rear Passenger Seat belt		350.00 ✓
1	Rear Passenger Seat brackets		220.00 X
1	Rear Tailgate glass	978.60	1481.30 ✓
1	Rear Glass Sealant		100.00
1	Rear passenger door rubber		868.00 X
1	Rear RH Fender Sealant		100.00 ✓
1	Rear end panel sealant		80.00
1	Sealant for rear passenger door rubber		750.00 X
			5831.30

LABOUR & MISC CHARGES

To dismantle / renew / knock / straighten the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.

1300
1500.00

To dismantle, remove and refit tailgate glass.

120.00 ✓

To dismantle, remove and refit RH side fender glass

150
250.00

To dismantle and refit rear passenger seat (RH) body panel inner trim board to facilitate repair.

200
380.00

To dismantle, remove and refit rear tailgate top spoiler, third light, School Bus Silhouette logo, rear speaker

80
200.00

To dismantle, remove and refit rear sensor, camera, wiper motor and checking of wiring.

120
280.00

Supply spray paint material and necessary items to respray the affected area rear RH / panel.

1100
1500.00

~~Labour charge for painting on Front damage portion.~~

~~1200.00~~

~~To dismantle, remove and refit tailgate component to replace tailgate, check and re-adjust the close gap and alignment tailgate glass~~

~~1500.00~~

2 To Repair Rear Passenger Seat (Both Side) - upholstery \$200 each 400.00 ✓

To Transfer rear tailgate gate lock, motor to facilitate repair wiring

60
180.00

FRONT PORTION

To straighten / align repair / knocking Front damaged portion and parts.

350
480.00

To Touch up painting on Front damage portion.

400
650.00
8640.00

Total: \$ 21,955.63