



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV12200/CHUA CHONG SIN Reg No/Reg Date SKL522S / 07/10/201 Date In/Mileage / 0 Chassis No GF7W0601792 Engine No 4J11BG1990 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/01/2021/ 10:56	BLE	261 / Edwin Caina	62185			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER & LHF FENDER 450X2								900 1800.00
E PNT98000 RESPRAY FRT BUMPER & LHF FENDER 350X2								700.00
M SUNDRY RENEW LHF SPORT RIM & TRANSFER TYRE / WHEEL BALANCING								30.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								120.00
USING HI-SCAN PRO TEST								
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								160.00
M SUNDRY APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS (Provide sales agreement)								20.00
M SUNDRY Sundries					1.00	859.00	23.00	661.43
M FACE,FR BUMPER / 00					1.00	515.00	23.00	396.55
M EXTENSION,FR BUMPER X NM					1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,LH / BR					1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER,LH / CUT					1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE X NM					1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE X NM					1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE X NM					1.00	359.00	23.00	276.43
M COVER,FR BUMPER X NM					1.00	688.00	23.00	529.76
M FENDER,FR LH / 00					1.00	116.00	23.00	89.32
M MOULDING,FR BUMPER,LH / CUT (fry hp)					1.00	160.00	23.00	123.20
M MOULDING,FR WHEEL ARCH,LH / CUT					1.00	974.00	23.00	749.98
M WHEEL,DISC LHF / CUT					1.00	1938.00	23.00	1492.26
M HEADLAMP ASSY,LH X NM								

Estimate

Steve CLKK

22/1/21, 11:00am

010

SURVEYOR NAME:

SURVEYOR SIGNATURE:

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: PIP

Confirm & accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill-effects

Authorized signatory and company stamp

DATE:

REMARKS:

Ry Bel SM
5 days
00-NM AL
EXIC - 7

Nett

7,642.35

7% GST on

7642.35

534.96

Total Payable

8,177.31

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.