



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

TP Chinn
Veron

JM6BN2278J0204980

Page No. 1

Vehicle No. SLZ
Stt5991C MAZDA 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	FRONT BUMPER <i>Distorted</i>		1055.50	✓
2	FRONT BUMPER SIDE RETAINER LH & RH @\$87.10 <i>2H Damaged</i>		174.20	45
2	FRONT BUMPER SIGNALLAMP LH & RH @\$419.50 <i>RH cracked</i>		839.00	312
2	FRONT BUMPER SIGNALLAMP COVER LH & RH @\$65.30 <i>RH del</i>		130.60	65.30
2	FRONT BUMPER SIGNALLAMP WIRELESS LH & RH @\$281.60 <i>RH Shipped</i>		563.20	281.60
2	FRONT BUMPER LAMP LH & RH @\$465.80 <i>RH cracked</i>		931.60	465.80
1	FRONT BUMPER LOWER GRILLE <i>Not Nec</i>		124.20	X
2	FRONT BUMPER LOWER GRILLE CAP LH & RH @\$51.00 <i>Not Nec</i>		102.00	X
1	FRONT BUMPER REINFORCEMENT <i>Distorted</i>		590.10	X
2	FRONT BUMPER REINFORCEMENT BRACKET LH & RH @\$110.20 <i>Not Nec</i>		220.40	X
1	FRONT BUMPER REINFORCEMENT PLATE SET <i>Not Nec</i>		120.80	X
1	FRONT GRILLE <i>cracked</i>		589.00	✓
1	FRONT GRILLE LOGO <i>Nec</i>		71.00	✓
2	FRONT GRILLE CHROME LH & RH @\$176.70 <i>RH at</i>		353.40	176.70
2	FRONT GRILLE BRACKET LH & RH @\$35.10 <i>RH Damaged</i>		70.20	35.10
2	FRONT GRILLE BRACKET PIN @\$18.90 <i>RH cracked</i>		37.80	18.90
2	FRONT GRILLE BRACKET PIN GROMMET @\$19.10 <i>Not Nec</i>		38.20	X
1	FRONT GRILLE UPPER GARNISH <i>Not Nec</i>		351.40	X
2	FRONT HEADLAMP LH & RH @\$3871.00 <i>RH cracked.</i>		7742.00	3871
1	FRONT HEADLAMP PANEL RH <i>Not Nec</i>		355.00	X
2	FRONT HEADLAMP BRACKET LH & RH @\$55.40 <i>Not Nec</i>		110.80	X
1	FRONT BONNET <i>Repair</i>		1259.00	X
2	FRONT BONNET HINGE LH & RH @\$81.00		162.00	X
1	FRONT BONNET STAY (HOLDER)	<i>Not Nec</i>	55.00	X
1	FRONT BONNET WEATHERSTRIP (OUTER)	<i>Not Nec</i>	60.80	X
2	FRONT FENDER LH & RH @\$417.50 <i>RH Distorted</i>		835.00	417.50
2	FRONT FENDER INNER SHIELD LH & RH @\$185.50 <i>RH Deformed</i>		371.00	185.50
2	FRONT FENDER STAY LH & RH @\$151.50 <i>RH Bent</i>		303.00	151.50
1	FRONT FENDER WHEEL HOUSE RH <i>Repair</i>		786.10	X
1	FRONT SUPPORT PANEL <i>Not Nec</i>		477.00	X
2	FRONT SUPPORT PANEL SIDE BRACKET @\$58.00 <i>Not Nec</i>		116.00	X
1	FRONT UPPER SUPPORT PANEL <i>Not Nec</i>		150.00	X
1	FRONT SPARE TANK <i>Not Nec</i>		161.20	X
1	FRONT WIPER TANK <i>Deformed</i>		243.00	✓
1	FRONT ENGINE LOWER COVER <i>Not Nec</i>		161.00	X
1	FRONT WIPER GARNISH <i>Not Nec</i>		321.00	X
Front Bumper Sensor 250 ✓				
<i>Damaged</i>				
8862.70				
7090.16				
less 10%			20031.50	
			2003.15	10%
			18028.35	

20%

SPECIAL NETT ITEMS			
1 SET	FRONT BUMPER CLIPS <i>Neu</i>		100.00 30
1 SET	FRONT BONNET INSULATOR CLIPS <i>Neu Neu</i>		100.00 X
1 SET	FRONT FENDER INNER SHIELD CLIPS <i>Neu</i>		100.00 30
1	COOLANT <i>Neu</i>	650.	120.00 40.
1	FRONT TYRE RH <i>Neu m</i>		350.00 X
1	FRONT RIM RH <i>Neu</i>		550 ✓
Total Parts			19348.35

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLZ
~~SLT~~5991C MAZDA 3

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	600
3	To remove and refix wiring at damaged areas	120.00	30
4	To perform anti rust treatment on affected areas	80.00	60
5	To remove and replace front driver & passenger airbag	220.00 *	
6	To conduct water seepage test	120.00 *	
7	To check diagnostics of vehicle management / control unit, reser memories to specification etc	210.00 *	100
8	To perform wheel alignment	120.00 *	80
Labour Total :		4270.00	
TOTAL (PARTS & LABOUR):		23618.35	

23,868.35

Address by
H/S 21/01/21

05 Days

total: 9410.16

H/S: 7.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(810)