



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103428

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 17/05/2021  
Reference CC4/FCI21001065/T1es3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. JTY 6553  
Insured Veh. SHB 4822M  
Claim No. D20005112MFSH  
Policy No. D-18088937MFSH  
Accident Date 12/12/2020  
Inspection Date 22/01/2021

| Description         | Total         |
|---------------------|---------------|
| Survey Inspection   | 424.00        |
| Resurvey Inspection |               |
| Digital Photographs |               |
| Transportation      |               |
| <b>Subtotal</b>     | <b>424.00</b> |
| <b>GST (7%)</b>     | <b>29.68</b>  |
| <b>Grand Total</b>  | <b>453.68</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                            |                 |                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------|------------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                |                                                                                            |                 | Ref: CC4/FCI21001065/T1es3q2 |  |
|                                                                                                                                        |                                                                                            |                 | Date: 17/05/2021             |  |
|                                                                                                                                        |                                                                                            |                 | Code: FCI2                   |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                            |                 |                              |  |
| Insured Veh.                                                                                                                           | SHB 4822M                                                                                  | Veh. Inspected  | JTY 6553                     |  |
| Policy No.                                                                                                                             | D-18088937MFSH                                                                             | Coverage (\$)   | 0.00                         |  |
| Claim No.                                                                                                                              | D20005112MFSH                                                                              | Excess (\$)     | 0.00                         |  |
| Assign From                                                                                                                            | ERIC                                                                                       | Assign Date     | 22/01/2021                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                            |                 |                              |  |
| Make & Model                                                                                                                           | YAMAHA Y15ZR                                                                               | c.c             | 150                          |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                     | Year of Reg.    | 2020                         |  |
| Chassis No.                                                                                                                            | PMYUG0520L0114681                                                                          | Colour          | BLUE                         |  |
| Odometer                                                                                                                               | -                                                                                          | Steering        | IN ORDER                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                   | Modification    | NIL                          |  |
| General                                                                                                                                | GOOD                                                                                       |                 |                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                            |                 |                              |  |
|                                                                                                                                        | Size                                                                                       | Make            | Balance                      |  |
| R/H Front Tyre                                                                                                                         | 90/80 R17                                                                                  | DURO            | 5 mm                         |  |
| L/H Front Tyre                                                                                                                         |                                                                                            |                 | mm                           |  |
| R/H Rear Tyre                                                                                                                          | 120/70 R17                                                                                 | DURO            | 5 mm                         |  |
| L/H Rear Tyre                                                                                                                          |                                                                                            |                 | mm                           |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                            |                 |                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.<br>DAMAGES SEE DETAILS.                                               |                                                                                            |                 |                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                            |                 |                              |  |
| Accident Date                                                                                                                          | 12/12/2020                                                                                 | Inspection Date | 22/01/2021                   |  |
| Survey held at                                                                                                                         | KARZ WORK SOLUTIONS<br>53 UBI AVE 1 #02-24<br>PAYA UBI INDUSTRIAL PARK<br>SINGAPORE 408934 |                 |                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                            |                 |                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                            |                 |                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                            |                 |                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                            |                 | 5 Working Days               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTY 6553

| Qty | Description of Parts               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b> |                      |                           |                   |
| 1   | SET FRONT FORK                     | BENT                 | 600.00                    | 400.00            |
| 1   | FRONT FENDER                       | CUT                  | 250.00                    | 150.00            |
| 1   | FRONT SIGNAL LAMP LH               | NOT NECESSARY        | 120.00                    | -                 |
| 1   | FRONT FOG LAMP LH                  | NOT NECESSARY        | 150.00                    | -                 |
| 1   | FRONT HEADLAMP                     | CUT                  | 350.00                    | 200.00            |
| 1   | FRONT HEADLAMP FAIRING (CENTRE)    | CUT                  | 380.00                    | 220.00            |
| 1   | FRONT HEADLAMP FAIRING (LH)        | NOT NECESSARY        | 180.00                    | -                 |
| 1   | FRONT FAIRING INNER                | CUT                  | 450.00                    | 280.00            |
| 1   | FRONT FAIRING OUTER                | CUT                  | 380.00                    | 225.00            |
| 1   | FRONT LH FAIRING                   | CUT                  | 550.00                    | 350.00            |
| 1   | FRONT LH FAIRING LOWER             | NOT NECESSARY        | 420.00                    | -                 |
| 1   | REAR LH FAIRING                    | CUT                  | 500.00                    | 350.00            |
| 1   | PILLION HANDREST                   | CUT                  | 280.00                    | 180.00            |
| 1   | REAR SIGNAL LH                     | CUT                  | 120.00                    | 80.00             |
| 1   | CLUTCH LEVER                       | CUT                  | 90.00                     | 90.00             |
| 1   | BRAKE LEVER                        | BENT                 | 90.00                     | 90.00             |
| 1   | GEAR PEDAL                         | BENT                 | 90.00                     | 90.00             |
| 1   | STAND                              | TO REPAIR SEE LABOUR | 85.00                     | -                 |
| 1   | FOOTREST                           | BROKEN               | 95.00                     | 95.00             |
| 1   | SET WING MIRROR                    | CRACKED              | 150.00                    | 100.00            |
| 1   | SET BALANCER                       | MISSING              | 120.00                    | 80.00             |
| 1   | HANDLE BAR                         | BENT                 | 550.00                    | 235.00            |
|     | LESS 10% DISCOUNT                  |                      | -600.00                   | -321.50           |
|     |                                    |                      | 5,400.00                  | 2,893.50          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>   |                      |                           |                   |
| 1   | STICKER (SN)                       | CUT                  | 300.00                    | 150.00            |
| 1   | IU BRACKET (SN)                    | CUT                  | 156.00                    | 156.00            |
| 1   | IU UNIT BRACKET (SN)               | BENT                 | 110.00                    | 110.00            |
| 1   | FRONT NUMBER PLATE (SN)            | CUT                  | 50.00                     | 10.00             |
| 1   | SET GEAR SHIT SHAFT OIL SEAL (SN)  | NOT NECESSARY        | 24.00                     | -                 |

Report Ref No. CC4/FCI21001065/T1es3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                 | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| 2                                                                           | FORK OIL SEAL (SN)                                                                   | NECESSARY | 120.00                    | 60.00             |
| 1                                                                           | BOT FORK OIL (SN)                                                                    | NECESSARY | 60.00                     | 60.00             |
|                                                                             |                                                                                      |           | 820.00                    | 546.00            |
|                                                                             | <b><u>LABOUR</u></b>                                                                 |           |                           |                   |
|                                                                             | TO CHECK WIRING SYSTEM.                                                              |           | 60.00                     | 30.00             |
|                                                                             | TO REALIGN BODY FRAME .                                                              |           | 350.00                    | 100.00            |
|                                                                             | TO R&R SUSPENSION ,HANELE BAR ,HEADLAMP & FAIRING .INCLUSIVE OF THE REPAIR OF STAND. |           | 400.00                    | 200.00            |
|                                                                             | TO SPRAY FENDER ,SIDE FAIRINGS AND AFFECTED AREAS .                                  |           | 500.00                    | 200.00            |
|                                                                             |                                                                                      |           | 1,310.00                  | 530.00            |
| <b>GRAND TOTAL</b>                                                          |                                                                                      |           | <b>7,530.00</b>           | <b>3,969.50</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                      |           |                           | <b>3,200.00</b>   |

Report Ref No. CC4/FCI21001065/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JTY 6553

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. JTY 6553**

**RE-INSPECTION**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JTY 6553

RE-INSPECTION

