

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name
	Reg No/Reg Date
	Date In/Mileage
	Chassis No
	Engine No
	Make/Model
Colour/Trim	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	22/01/2021/ 15:00	QUD	247 / DonBong	62192	
Description of Goods / Services					Qty	Unit Price Disc% Amount
E PNT88000						2250.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 450X4						1800
FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER						
REPLACE FRONT BODY KITS, RH SIDE SKIRTING						
REPAIR RH FRONT DOOR, REPAIR TH SIDE PANEL,						100.00 X
E PNT88000						
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER (photo)						80.00 X
TO FACILITATE REPAIR WORK						
A 55900099						160.00
TOP UP AIR CON GAS AND CHECK A/CON SYSTEM						
E PNT88000						3150.00
REMOVE AND REPLACE FRONT BODY KITS AND RH SIDE SKIRTING						
E PNT98000						2450
PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET						
FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER,						
RH FRONT DOOR, RH SIDE SKIRTING, RH SIDE SILL PANEL 350 X 7						
AND AFFECTED PORTION						40 160.00
M SUNDRY						
APPLY BODY SEALANT						30.00
A 54900099						80.00 X
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM						
M SUNDRY						120.00
PERFORM RUST PREVENTION						
A WHEELALIGNMENTBP						30.00
To Conduct Computerize Full Wheel Alignment						
M SUNDRY						400 675.00
LABOUR RENEW RH SPORT RIM INCLUDING BALANCING						
A 33900099						300.00
RENEW FRT U/CARRIAGE DAMAGES						
M SUNDRY						
SUPPLY RH FRONT TIRE						30 50.00
M SUNDRY						
SUNDRIES						

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10233/TOH YAN LING, PHYLLICIA (ZHUO Y Reg No/Reg Date SMH3977R / 22/01/201 Date In/Mileage / 34424 Chassis No MMBSTA13AJH004474 Engine No 3A92UHK3324 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	22/01/2021/ 15:00	QUD	247 / DonBong	62192		
Description of Goods / Services			Qty	Unit Price	Disc%	Amount	
M	PANEL, HEADLAMP SUPPORT, UPR	BT	1.00	66	65.00	23.00	50.05
M	PANEL ASSY, FR END	DD	1.00		1055.00	23.00	812.35
M	CONDENSER ASSY, A/C REFRIGE	X NAI	1.00		758.00	23.00	583.66
M	PANEL, AIR GUIDE	X NAI	1.00		112.00	23.00	86.24
M	RADIATOR ASSY	X NAI	1.00		967.00	23.00	744.59
M	PANEL, AIR GUIDE, RH	X NAI	1.00		11.00	23.00	8.47
M	PANEL, AIR GUIDE, LH	X NAI	1.00		11.00	23.00	8.47
M	LLC 4L	X NAI	1.00		26.00	23.00	20.02
M	COVER, ENG ROOM UNDER, FR	X NAI	1.00		99.00	23.00	76.23
M	CLIP, FR BUMPER	MC	10.00		4.00	23.00	30.80
M	TANK, WINDSHIELD WASHER	CRU	1.00	75	74.00	23.00	56.98
M	MOTOR, WINDSHIELD WASHER	CR	1.00		30.00	23.00	23.10
M	GASKET, W/SHLD WASHER MOTOR	MC	1.00		4.00	23.00	3.08
M	CAP, WASHER TANK FILLER	X NAI	1.00		7.00	23.00	5.39
M	HEADLAMP ASSY, LH	BR	1.00	663	660.00	23.00	508.20
M	HEADLAMP ASSY, RH	MIS	1.00	663	660.00	23.00	508.20
M	GRILLE, RADIATOR	X NAI	1.00		554.00	23.00	426.58
M	BRACKET, FR BUMPER, LH	X NAI	1.00		13.00	23.00	10.01
M	BRACKET, FR BUMPER, RH	MIS	1.00		13.00	23.00	10.01
M	COVER, HEADLAMP SUPT PANEL	CRU	1.00		62.00	23.00	47.74
M	GRILLE, FR UNDER	X NAI	1.00		165.00	23.00	127.05
M	FACE, FR BUMPER	BR	1.00	706	703.00	23.00	541.31
M	MARK, THREE-DIA	MC	1.00	70	69.00	23.00	53.13
M	GARNISH, FR BUMPER, RH	(fay krp) - CUT	1.00		127.00	23.00	97.79
M	COVER, FR BUMPER	X NAI	1.00		12.00	23.00	9.24
M	CLIP, FR BUMPER	MC	10.00		4.00	23.00	30.80
M	HOOD	DD	1.00	737	734.00	23.00	565.18
M	HINGE, HOOD, LH	X NAI	1.00		56.00	23.00	43.12
M	HINGE, HOOD, RH	X NAI	1.00		56.00	23.00	43.12
M	INSULATOR, HOOD	X NAI	1.00		177.00	23.00	136.29
M	CLIP, HOOD INSULATOR	MC	5.00		3.00	23.00	11.55
M	LATCH, HOOD	X NAI	1.00		69.00	23.00	53.13
M	ROD, HOOD SUPPORT	BT	1.00		37.00	23.00	28.49

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10233/TOH YAN LING, PHYLLICIA (ZHUO Y Reg No/Reg Date SMH3977R / 22/01/201 Date In/Mileage / 34424 Chassis No MMBSTA13AJH004474 Engine No 3A92UHK3324 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	22/01/2021/ 15:00	QUD	247 / DonBong	62192				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
M	FENDER,FR RH	DU			1.00	509	497.00	23.00	382.69
M	EMBLEM ECO	ARC			1.00		17.00	00.00	17.00
M	SHIELD,FR WHEELHOUSE,RH	CRM			1.00		98.00	23.00	75.46
M	CLIP,FENDERSHIELD	ARC			10.00		4.00	23.00	30.80
M	CROSSMEMBER,FR AXLE,NO.1	BT			1.00	868	864.00	23.00	665.28
M	ARM ASSY,FR SUSP,LWR RH	BT			1.00	280	278.00	23.00	214.06
M	STRUT,FR SUSP	BT			1.00	456	452.00	23.00	348.04
M	DAMPER,FR SUSP STRUT	ARC			1.00		24.00	23.00	18.48
M	PAD,FR SUSP SPRING	ARC			1.00		17.00	23.00	13.09
M	SEAT,FR SUSP SPRING,UPR	BT			1.00		37.00	23.00	28.49
M	BEARING,FR SUSP STRUT	ARC			1.00		9.00	23.00	6.93
M	SUPPORT,FR SUSP STRUT	X NN			1.00		17.00	23.00	13.09
M	INSULATOR,FR SUSP STRUT	ARC			1.00	84	83.00	23.00	63.91
M	INSULATOR,FR SUSP STRUT	X NN			1.00		98.00	23.00	75.46
M	GEAR & LINK ASSY,STEERING	X NN			1.00		1444.00	23.00	1111.88
M	END ASSY,TIE ROD	X NN			1.00		52.00	23.00	40.04
M	HUB ASSY,FR WHEEL	ARC			1.00	242	240.00	23.00	184.80
M	SNAP RING,FR WHEEL HUB	ARC			1.00		8.00	23.00	6.16
M	BEARING,FR WHEEL HUB	ARC			1.00	122	121.00	23.00	93.17
M	KNUCKLE,RH	BT			1.00	367	365.00	23.00	281.05
M	COVER,FR BRAKE DISC	X NN			1.00		26.00	23.00	20.02
M	SHAFT AS,FR AXLE DRIVE,RH	X NN			1.00		1201.00	23.00	924.77
M	WHEEL,DISC	CUT			1.00		687.00	23.00	528.99
M	BODY KIT, ATTRAGE	X BR (Salvage from SGW 58094)			1.00		1643.00	00.00	1643.00

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: OO- Nt AutL

DATE: Express - ?

REMARKS: 22/1/21, 4.00pm

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: OO-NH AutL

DATE: Express - ?

REMARKS: 22/1/21, 4.30pm

Confirm & accepted by

Ry Bel SPJ
12 days

Nett

19,732.03

19732.03

1381.24

Total Payable

21,113.27

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.