



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10233/TOH YAN LING, PHYLLICIA (ZHOU Y Reg No/Reg Date SMH3977R / 22/01/201 Date In/Mileage / 34424 Chassis No MMBSTA13AJH004474 Engine No 3A92UHK3324 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	22/01/2021/ 15:00	QUD	247 / DonBong	62192		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER REPLACE FRONT BODY KITS, RH SIDE SKIRTING REPAIR RH FRONT DOOR, REPAIR TH SIDE PANEL,				450 X 4			2250.00
E PNT88000 REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK				(photo)			100.00
A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM							80.00
E PNT88000 REMOVE AND REPLACE FRONT BODY KITS AND RH SIDE SKIRTING							160.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, RH FRONT DOOR, RH SIDE SKIRTING, RH SIDE SILL PANEL AND AFFECTED PORTION				350 X 7			3150.00
M SUNDRY APPLY BODY SEALANT							160.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
M SUNDRY PERFORM RUST PREVENTION							80.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY LABOUR RENEW RH SPORT RIM INCLUDING BALANCING							30.00
A 33900099 RENEW FRT U/CARRIAGE DAMAGES							675.00
M SUNDRY SUPPLY RH FRONT TIRE							300.00
M SUNDRY SUNDRIES							50.00

**Estimate**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10233/TOH YAN LING, PHYLLICIA (ZHUO Y Reg No/Reg Date SMH3977R / 22/01/201 Date In/Mileage / 34424 Chassis No MMBSTA13AJH004474 Engine No 3A92UHK3324 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/01/2021/ 15:00	QUD	247 / DonBong	62192
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M PANEL, HEADLAMP SUPPORT, UPR	BT	1.00	65.00	23.00	50.05
M PANEL ASSY, FR END	?	1.00	1055.00	23.00	812.35
M CONDENSER ASSY, A/C REFRIGE	X	1.00	758.00	23.00	583.66
M PANEL, AIR GUIDE	?	1.00	112.00	23.00	86.24
M RADIATOR ASSY	X	1.00	967.00	23.00	744.59
M PANEL, AIR GUIDE, RH	X	1.00	11.00	23.00	8.47
M PANEL, AIR GUIDE, LH	X	1.00	11.00	23.00	8.47
M LLC 4L	X	1.00	26.00	23.00	20.02
M COVER, ENG ROOM UNDER, FR	?	1.00	99.00	23.00	76.23
M CLIP, FR BUMPER	RC	10.00	4.00	23.00	30.80
M TANK, WINDSHIELD WASHER	CRU	1.00	74.00	23.00	56.98
M MOTOR, WINDSHIELD WASHER	BR	1.00	30.00	23.00	23.10
M GASKET, W/SHLD WASHER MOTOR	RC	1.00	4.00	23.00	3.08
M CAP, WASHER TANK FILLER	X	1.00	7.00	23.00	5.39
M HEADLAMP ASSY, LH	BR	1.00	660.00	23.00	508.20
M HEADLAMP ASSY, RH	MIS	1.00	660.00	23.00	508.20
M GRILLE, RADIATOR	?	1.00	554.00	23.00	426.58
M BRACKET, FR BUMPER, LH	X	1.00	13.00	23.00	10.01
M BRACKET, FR BUMPER, RH	MIS	1.00	13.00	23.00	10.01
M COVER, HEADLAMP SUPT PANEL	CRU	1.00	62.00	23.00	47.74
M GRILLE, FR UNDER	?	1.00	165.00	23.00	127.05
M FACE, FR BUMPER	BR	1.00	703.00	23.00	541.31
M MARK, THREE-DIA	RC	1.00	69.00	23.00	53.13
M GARNISH, FR BUMPER, RH	(fry krp) - CUT	1.00	127.00	23.00	97.79
M COVER, FR BUMPER	?	1.00	12.00	23.00	9.24
M CLIP, FR BUMPER	RC	10.00	4.00	23.00	30.80
M HOOD	OO	1.00	734.00	23.00	565.18
M HINGE, HOOD, LH	?	1.00	56.00	23.00	43.12
M HINGE, HOOD, RH	?	1.00	56.00	23.00	43.12
M INSULATOR, HOOD	X	1.00	177.00	23.00	136.29
M CLIP, HOOD INSULATOR	RC	5.00	3.00	23.00	11.55
M LATCH, HOOD	X	1.00	69.00	23.00	53.13
M ROD, HOOD SUPPORT	BT	1.00	37.00	23.00	28.49

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10233/TOH YAN LING, PHYLLICIA (ZHUO Y Reg No/Reg Date SMH3977R / 22/01/201 Date In/Mileage / 34424 Chassis No MMBSTA13AJH004474 Engine No 3A92UHK3324 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/01/2021/ 15:00	QUD	247 / DonBong	62192			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	FENDER,FR RH	DU			1.00	497.00	23.00	382.69
M	EMBLEM ECO	ARC			1.00	17.00	00.00	17.00
M	SHIELD,FR WHEELHOUSE,RH	CRU			1.00	98.00	23.00	75.46
M	CLIP,FENDERSHIELD	ARC			10.00	4.00	23.00	30.80
M	CROSSMEMBER,FR AXLE,NO.1	BT			1.00	864.00	23.00	665.28
M	ARM ASSY,FR SUSP,LWR RH	BT			1.00	278.00	23.00	214.06
M	STRUT,FR SUSP	BT			1.00	452.00	23.00	348.04
M	DAMPER,FR SUSP STRUT	nec			1.00	24.00	23.00	18.48
M	PAD,FR SUSP SPRING	ARC			1.00	17.00	23.00	13.09
M	SEAT,FR SUSP SPRING,UPR	BT			1.00	37.00	23.00	28.49
M	BEARING,FR SUSP STRUT	ARC			1.00	9.00	23.00	6.93
M	SUPPORT,FR SUSP STRUT	?			1.00	17.00	23.00	13.09
M	INSULATOR,FR SUSP STRUT	?			1.00	83.00	23.00	63.91
M	INSULATOR,FR SUSP STRUT	?			1.00	98.00	23.00	75.46
M	GEAR & LINK ASSY,STEERING	?			1.00	1444.00	23.00	1111.88
M	END ASSY,TIE ROD	?			1.00	52.00	23.00	40.04
M	HUB ASSY,FR WHEEL	?			1.00	240.00	23.00	184.80
M	SNAP RING,FR WHEEL HUB	?			1.00	8.00	23.00	6.16
M	BEARING,FR WHEEL HUB	?			1.00	121.00	23.00	93.17
M	KNUCKLE,RH	?			1.00	365.00	23.00	281.05
M	COVER,FR BRAKE DISC	X			1.00	26.00	23.00	20.02
M	SHAFT AS,FR AXLE DRIVE,RH	?			1.00	1201.00	23.00	924.77
M	WHEEL,DISC	CUT			1.00	687.00	23.00	528.99
M	BODY KIT, ATTRAGE	X			1.00	1643.00	00.00	1643.00

Estimate

SURVEYOR NAME : Steve (LKK)

SURVEYOR SIGNATURE : OD-NH AutL

DATE : Express - ?

REMARKS : 22/1/21, 4.00pm

OR (Salvage from SGW 5809Y)

SURVEYOR NAME :

Steve (LKK)

SURVEYOR SIGNATURE :

OO-NH AutL

DATE :

Express - ?

REMARKS :

22/1/21, 4.00pm

P/P

Confirm &amp; accepted by

Ry BL Sry

12 days

Nett

19,732.03

19732.03

1381.24

Total Payable

21,113.27

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.