版 CS/VO121001088/Q+f3 ASS. REC. BY: Sun Pin ASSIGNMENT AFX 7094 Yr Regn: From: Veh No: Date: Type: M.Car / M.Cycle / Bus /(Van) / Lorry / Taxi / Prime Mover / Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or To Inspect Vehicle No: c.c 1488 Nissan Vahette. Make: at Workshop m/s Insured / Std / NI / NA white. A/C: Colour of T/Radio: Insured / Std / NI / NA Sp.Reading 389135 Insured: Eng/No: Policy No. PN&VPC22JTCA57418. C/No: Gen. Cond: Good (Fair / Poor / Burnt Claims No. Steering: Inorden/ Jammed / Leaked / Burnt or Sum Insured: Excess: loorde / Jammed / Leaked / Burnt or Brake: (Client's Record) Modi: Nil / S/Rim / STO A/Rim or Make of Veh: 175R /1C Tyre Size: 175 R 13 C (Policy Condition) O/S Remark: The veh had commenced its BS / DUN / EXNOVA GYY FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO / YOKO or Front Bal. or Market Value: Rear Consistent?: Yes or No R/Bal. R/Bal. mm IDAC Accident Rport: 6 L/Bal. L/Bal. Consistent?: Yes or No mm mm GIA / PR Seen: D.O.A. 13/61/2021 D.O.I. 26/01/2021 Res.: Yes or No days Est. Repairs: 3 Val.: Yes or No Lum Sum: Survey held at Siong Lee Des. of Damages : Frt / Rean / O/S / N/S / U/C / Rooftop or CA | REV | REP. | 24 HRS Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Action / Instruction Date / Time \* pending loy card and Insurance Certificate. Date/Time, File Pass to? Days Of Repair: : Preli. Report ; Final Report Resurvey No. of Trip: Survey Fee: Date/Time, File Return to? Transportation: Add Fee: : Site Insp \_S + RS.\_\_SI : Interview (\$ Photos Tech. Invs (\$ บัตกลดร Reperformat: Weekend (% Lump Sum / LBJ: (%

TOTAL





1 of 3 Report No. T/20210113/2186

Police Station Of Origin: Bukit Panjang North NPP 27 Marsiling Drive #01-237 SINGAPORE 730027

Tel No: 1800-3689999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:

Vide Report No.: Station Diary No.: 33

13/01/2021 20:16 Informant's Particulars Address: Name of Informant: APT BLK 26 Marsiling Drive #13-231 SINGAPORE 730026 ONG CHIN HUE Contact No.: ID Type / ID No.: Mobile: 85080493 Home/Office: FIN NO / F8423760N Email: Nationality: MALAYSIAN Type of Informant: Date of Birth: Sex: Age: Driver 03/12/1976 44 Male Institution / School Name: Language: Race: Chinese Chinese Driving Licence Information: Occupation: Date of Expiry: Class: 2B,3 Construction General Information of the Asciden Type of Location: Date/Time of

Type of Accident:	Non-Injury Foreign Vehicle	Drive:	Accident: 13/01/2021 08:50	Straight Road
Location:	:	, , , , , , , , , , , , , , , , , , ,		
CHOA CHU K	ANG WAY	·	,	
Weather:		Road Surface: Dry	Ro	ad Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled	Mo	affic Volume: oderate
Type of Collisi	on: ng Vehicles - Head To R	ear	1	nyone conveyed by nbulance: o

Details of Vehicle Involved								
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger		
AFX7094	Van				Slightly	0 .		
Al XI,004		¥			Damaged			
SGG6481K	Car		,		Slightly	0		
00004011K			,		Damaged			

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20210113/2186

Police Station Of Origin: Bukit Panjang North NPP 27 Marsiling Drive #01-237 SINGAPORE 730027

Tel No: 1800-3689999

#### **CONTINUATION OF REPORT**

Driver		Company of the state of	And the second		
Name	ONG CHIN HUE			ID No.	F8423760N
Related Vehicle	AFX7094 (Van)			Contact No.	85080493
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	,	Date Disch	narge NIL	. (
No. of Days grant	ted Medical Leave	NIL	Degree of	Injury NIL	

### Brief Details.

V1) AFX7094

V2) SGG6841K

On the above mentioned date, time and location, I was driving V1 along Choa Chu Kang Way towards to KJE. I was waiting for the T-junction traffic light to the green. While waiting, I felt an impact from the back. After which, I alighted and made a checked. I then discovered that my rear door was damaged and due to the damaged the door unable to close fully.

I observed that V2 was behind V1. V2 sustained damaged at the front bumper. No injury on both parties. No police or ambulance was activated. No government property was damaged. I am lodging this report for insurance purpose.





3 of 3

Report No. T/20210113/2186

Police Station Of Origin: Bukit Panjang North NPP 27 Marsiling Drive #01-237 SINGAPORE 730027

Tel No: 1800-3689999

## Sketch Plan

NP168

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

**CONTINUATION OF REPORT** 

CP 137	
Signature Of Officer Recording The Report:	Signature Of Informant:
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Staff Sgt Alk QISONG Signature:	. 7
Millian Millian State St	Data /Times
Signature Of Interpreter	Date/Time: 13/01/2021 20:16
Not applicable	10/01/2021 20:10
	Classification Of Case:
Officer In Charge Of Case:	Classification Of Case.
TP / AEIT / Sgt 3 MUHAMMAD RIZWAN BIN KAMALUDIN	
Contact No.: 65476185	
Authentication Stamp	

# TWIN WHEELS AUTO TRADING ENTERPRISE

38 Woodlands Industrial Park E1 #03-14

Singapore 757700

TEL: 6457 0410 / 6765 2616 EMAIL: twinauto@singnet.com.sg

26 January 2021

ATTN: MOTOR CLAIM DEPARTMENT

**ATTN: ONG CHIN HUE** 

H/P: 8508 0493

Dear Sirs / Madam,

Accident Claim for Vehicle No.AFX 7094, Involving Vehicle No.SGG 6481 K. Accident on 13 JANUARY 2021, AT CHOA CHU KANG WAY.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	TAILGATE / DP	1PC	\$ 1,850.00
2	TAILGATE LOCK / Jum	1PC	\$ 320.00
3	TAILGATE LOCK CATCH X	1PC	\$ 80.00
4	TAILGATE WHEATHER STRIP / CN4	1PC	\$ 300.00
5	TAILGATE WINDSCREEN RUBBER / Ne(	1PC	\$ 380.00
6	TAILLAMP RA & X	12PCS	\$ 780.00
7	TAILGATE LAMP KH ?	1 ZPCS	\$ 660.00
8	TAILGATE HINGES X	2PCS	\$ 180.00
9	REAR BUMPER / (MM	1PC	\$ 550.00
10	REAR BUMPER REINFORCEMENT 2	1PC	\$ 450.00
11	REAR END PANEL X K	1PC	\$ 480.00
12	REAR SPARE TYRE TRAY	1PC	\$ 320.00
13	REAR SHOCK ABSORBER X	2PCS	\$ 650.00
	TOTAL LIST PRICE		\$ 7,000.00
	LESS 20%		\$ (1,400.00)
	TOTAL AMOUNT		\$ 5,600.00

5	PARTS REPLACEMENT	QTY	SPEC	IAL NETI	PRICE
1	REAR BUMPER REVERSE SENSOR Shu	1SET	\$	Z <b>O</b>	280.00
1	TOTAL SPECIAL NETT PRICE		\$		280.00
	LABOUR:			1000	850.00
1	LABOUR TO SPRAY PAINT		\$	600	
2	LABOUR TO PANEL BEATING		\$	500	900.00
				1 .	1 10 00
3	LABOUR TO DISMANTLE & REFIX TAILGATE		\$	100	140.00
3	WINDSCREEN GLASS.				
	LABOUR TO APPLY RUST-PROOFING ON REPAIRED		\$	40	200.00
4	AND REPLACED PARTS			C	2 222 22
	TOTAL L.	ABOUR	\$		2,090.00
	TOTAL AN	10UNT	\$	7	7,970.00

THANK YOU

FROM:

### Twin Wheels Auto Trading Enterprise

Mr Tan Leng Huat

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: