

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized
L1Pn @ 1900h
The Wong Ahu Paim
-3 days

REPAIR ESTIMATE FOR GBJ5121A

No.	Qty	List Items	
1	1	Front bumper	\$ CM 507.40 ✓
2	1	Front bumper LH tow cover	\$ Sn 32.00 X
3	1	Front bumper LH side retainer	\$ Sn 191.30 X
4	1	Front bumper inner reinforcement	\$ Bn 379.20 ✓
5	1 set	Front bumper clips	\$ Sn 40.00 ✓
6	1	LH headlamp	\$ Mjcm 748.10 ✓
7	1	Front grille assy 490.90	Mj \$ CM 580.80 ✓
8	1	Front bonnet	\$ R 756.60 X
9	1	Front bonnet centre "TOYOTA" logo	\$ Sn 66.10 X
			\$ 3,301.50
Less 25%			\$ 825.38
Total :			\$ 2,476.13

Special Nett Items

10	1	Front number plate	\$ Bn 45.00 25sn
----	---	--------------------	------------------

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 600.00 35cl
2	To putty and spray Spray Paintings charges.	\$ 800.00 40cl
3	To check wirings & lightings.	\$ 40.00 2cl
4	To supply and apply anti rust treatment	\$ Sn 50.00 X
Total :		\$ 1,490.00

Total Parts and Labour : \$ 4,011.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: