

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9833Z**AAD2101-103***Not Notified**Return 139 part*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

25 JAN 2021**SHB9833Z**

JTDKB3FU003092305

TOYOTA

PRIUS GEN 4

22/01/2021

III

23/10/2020

PART	LIST
1 HOOD SUB-ASSY	\$ 983.10 X
1 LOCK ASSY, HOOD	\$ 135.00 X
1 HINGE ASSY, HOOD, LH	\$ 58.90 ?
1 HINGE ASSY, HOOD, RH	\$ 58.90 ?
1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$ 100.40 X
1 COVER, FRONT BUMPER	\$ 521.00 ✓
1 ABSORBER, FRONT BUMPER ENERGY	\$ 80.20 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ 716.60 X
1 COVER, FRONT BUMPER HOLE, RH	\$ 30.20 X
1 MOULDING, FRONT BUMPER SIDE, RH	\$ 95.60 ✓
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$ 47.50 X
1 BRACKET, FRONT BUMPER SIDE, RH	\$ 59.30 ✓
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ 80.10 X
1 LINER, FRONT FENDER, RH	\$ 202.50 ✓
1 COVER, RADIATOR SUPPORT OPENING	\$ 211.50 X
1 FENDER SUB-ASSY, FRONT RH	\$ 977.80 ✓
1 EMBLEM, SIDE PANEL, RH	\$ 54.60 ✓
1 BRACKET, HEADLAMP, RH	\$ 34.80 X
1 MOTOR, HEADLAMP LEVELING, RH	\$ 487.50 ?
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$ 3,772.50 ?
1 UNIT ASSY, HEADLAMP, RH	\$ 2,637.60 ✓
1 GRILLE SUB-ASSY, RADIATOR	\$ 422.50 ✓
1 JAR ASSY, WINDSHIELD WASHER	\$ 219.10 X
TOTAL	\$ 11,987.20
25%	\$ 2,828.00
	\$ 8,484.00

Special Nett

Trans-cab Auto Services Pte Ltd

AAD2101-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9833Z

1SET FRONT FENDER CLIP

1SET FRONT FENDER LINER CLIP

1SET FRONT BUMPER CLIP

1 TYRE

1 RIM

\$	65.00	✓
\$	75.00	X
\$	90.00	50%
\$	350.00	X
\$	1,879.40	X
TOTAL	\$ 2,459.40	

TOTAL PARTS \$ 9,530.50**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion,
Remove And Renewal Of Parts, Adjust And Realign The Same
To remove and refit interior fittings, trimings, garnish, fittings and
other, to enable repair.

\$ 1,600.00 50%

\$ 380.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 30%

To check steering geometry and computer wheel alignment

\$ 220.00 60%

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 66%

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 20%

TOTAL \$ 4,380.00**Over All Total \$ 15,323.40****(PART-BY-PART) Repair Days****20 days**
3 days

- LKK Auto Consultants** hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: