

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9833Z**AAD2101-103***Not Authorised**Recovery B&P*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

25 JAN 2021**SHB9833Z**

JTDKB3FU003092305

TOYOTA

PRIUS GEN 4

22/01/2021

III

23/10/2020

	PART
1	HOOD SUB-ASSY
1	LOCK ASSY, HOOD
1	HINGE ASSY, HOOD, LH
1	HINGE ASSY, HOOD, RH
1	COVER SUB-ASSY, FRONT PILLAR, UPR RH
1	COVER, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	COVER, FRONT BUMPER HOLE, RH
1	MOULDING, FRONT BUMPER SIDE, RH
1	STAY SUB-ASSY, FRONT BUMPER, RH
1	BRACKET, FRONT BUMPER SIDE, RH
1	SUPPORT, FRONT BUMPER SIDE, RH
1	LINER, FRONT FENDER, RH
1	COVER, RADIATOR SUPPORT OPENING
1	FENDER SUB-ASSY, FRONT RH
1	EMBLEM, SIDE PANEL, RH
1	BRACKET, HEADLAMP, RH
1	MOTOR, HEADLAMP LEVELING, RH
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
1	UNIT ASSY, HEADLAMP, RH
1	GRILLE SUB-ASSY, RADIATOR
1	JAR ASSY, WINDSHIELD WASHER

LIST

\$	<i>R</i>	983.10	X
\$	<i>R</i>	135.00	X
\$	<i>R</i>	58.90	X
\$	<i>R</i>	58.90	X
\$	<i>Sm</i>	100.40	X
\$	<i>CM</i>	521.00	✓
\$	<i>Sm</i>	80.20	X
\$	<i>R</i>	716.60	X
\$	<i>Sm</i>	30.20	X
\$	<i>And</i>	95.60	✓
\$	<i>R</i>	47.50	X
\$	<i>diy</i>	59.30	✓
\$	<i>Sm</i>	80.10	X
\$	<i>diy</i>	202.50	✓
\$	<i>Sm</i>	211.50	X
\$	<i>R</i>	977.80	✓
\$	<i>R</i>	54.60	✓
\$	<i>Sm</i>	34.80	X
\$	<i>Sm</i>	487.50	X
\$	<i>Sm</i>	3,772.50	X
\$	<i>CM</i>	2,637.60	✓
\$	<i>diy</i>	422.50	✓
\$	<i>Sm</i>	219.10	X

TOTAL	\$	11,987.20
25%	\$	2,828.00
	\$	8,484.00

Special Nett

Trans-cab Auto Services Pte Ltd

AAD2101-103

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9833Z

1SET FRONT FENDER CLIP	\$	65.00	✓
1SET FRONT FENDER LINER CLIP	\$	75.00	X
1SET FRONT BUMPER CLIP	\$	90.00	50sm
1 TYRE	\$	350.00	X
1 RIM	\$	1,879.40	X
TOTAL	\$	2,459.40	

TOTAL PARTS \$ 9,530.50**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	500l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	30l
To check steering geometry and computer wheel alignment	\$	220.00	60l
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	660l
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20l
TOTAL	\$	4,380.00	

Over All Total \$ 15,323.40**(PART-BY-PART) Repair Days**20 days
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: