



CYCLE & CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13459/NG KIA WHYE, ADRIAN(WU JIAWEI) Reg No/Reg Date SFA1778G / 24/11/202 Date In/Mileage 25/01/2021/ 0 Chassis No KNAE351AML6090665 Engine No G4KLLH031295 Make/Model KIA/STINGER 2.0 A GAA3 RED LEATHER Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	23/01/2021/ 09:43	QUK	282 / Kevin Leong	27889

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER, FRT RH HEAD LAMP & AFFECTED AREA				400 800.00
E PNT98000 PAINT WORK ON FRONT BUMPER PANEL				350 700.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				20 50.00
M LAMP ASSY-HEAD,RH	1.00	3977.00	20.00	3181.60
M ABSORBER-FRONT BUMPER ENERGY	1.00	105.00	20.00	84.00
M GRILLE-FRONT BUMPER	1.00	391.00	20.00	312.80
M COVER-FR BUMPER	1.00	646.00	20.00	516.80
M LIP ASSY-FRONT BUMPER	1.00	22.00	20.00	17.60
M COVER ASSY-AIR CURTAIN,RH	1.00	126.00	20.00	100.80
M AIR DUCT-FR BUMPER,RH	1.00	24.00	20.00	19.20
M BRKT ASSY-FRT BUMPER SIDE MTG.	1.00	15.00	20.00	12.00
M KIA STINGER BODYKIT	1.00	2442.00	00.00	2442.00

Estimate

Steve CLKK) 25/1/21, 2.30pm

OD - NM A/L

Excess - ?

PIP

My BL spy

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Confirm & accepted by [Signature] from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7% GST on	Nett	8,386.80
		587.08
	Total Payable	8,973.88

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.