



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 22.01.2021
Emailed : 10.02.2021, 9.40am
Date Survey : 25.01.2021

VEHICLE NO : SLX 7631 P
MODEL : MIT OUTLANDER 2.0
WIP : 62199

Material	:	\$	<u>6,024.62</u>
Labour	:	\$	<u>2,780.00</u>
Sub-Total	:	\$	<u>8,804.62</u>
REPAIR LIMIT	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>8,804.62</u>
GST 7%	:	\$	<u>616.32</u>
Grand Total	:	\$	<u>9,420.94</u>
Finalise By/Date	:	<u>LOI / 10/02/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 26/01/2021	Cust No/Name	KCV16223/Kamarul Zaman Bin Ramli
	Reg No/Reg Date	SLX7631P / 11/04/2018
	Date In/Mileage	26/01/2021/ 74210
	Chassis/Package	GF7W0401070 /#
	Engine No	4J11XK6129
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (992)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	09/02/2021/ 10:07	BLE	260 / AiTing	62199			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, FRONT BUMPER BODY KIT, LH FRONT FENDER, REPAIR LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 900.00
E PNT98000 RESPRAY ON FRONT BUMPER, FRONT BUMPER BODY KIT, LH FRONT FENDER, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1400.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT								✓ 120.00
M SUNDRY APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS								✓ 160.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB REPLACE LH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								✓ 30.00
X FACE,FR BUMPER					1048 1.00	✓ 859.00	23.00	661.43
X GARNISH,FR BUMPER,LH					1.00	✓ 75.00	23.00	57.75
X BRACKET,FR BUMPER SIDE,LH					1.00	✓ 18.00	23.00	13.86
X GARNISH,FR BUMPER SIDE					1.00	✓ 48.00	23.00	36.96
X GARNISH,FR BUMPER SIDE					1.00	✓ 220.00	23.00	169.40
X GARNISH,FR BUMPER SIDE					1.00	✓ 112.00	23.00	86.24
X FENDER,FR LH					1.00	✓ 688.00	23.00	529.76
X SHIELD,FR WHEELHOUSE,LH					1.00	✓ 164.00	23.00	126.28
X MOULDING,FR BUMPER,LH					1.00	✓ 116.00	23.00	89.32
X MOULDING,FR WHEEL ARCH,LH					1.00	✓ 199.00	23.00	153.23
X HEADLAMP ASSY,LH					1.00	✓ 2125.00	23.00	1636.25
X AERO KIT - OUTLANDER					1.00	✓ 1554.00	00.00	1554.00
X WHEEL,SPARE TIRE DISC LHF					1.00	✓ 1102.00	23.00	848.54

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 26/01/2021	Cust No/Name	KCV16223/Kamarul Zaman Bin Ramli
	Reg No/Reg Date	SLX7631P / 11/04/2018
	Date In/Mileage	26/01/2021/ 74210
	Chassis/Package	GF7W0401070 /#
	Engine No	4J11XK6129
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (992)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	09/02/2021/ 10:07	BLE	260 / AiTing	62199		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	CLIP,ENG ROOM COVER	} Supp.		10.00	2.00	23.00	15.40
X	CLIP,RR BUMPER			10.00	3.00	23.00	23.10
X	RIVET,FR BUMPER			6.00	5.00	23.00	23.10
Z	TEXT						
	AIG OD CLAIM						
	DOA : 22.01.21						
	SURVEYOR STEVE LKK 25.01.21						
	POLICY NO : 1800035674-01						
Pro Forma							
Guarantee Your Warranty, Maintain with Cycle & Carriage!							

Parts	6,024.62	Nett	8,804.62
Labour	2,570.00	7% GST on	616.32
Standard Menu	0.00		
Specialist Job	30.00	Total Payable	9,420.94
Diagnostics Job	0.00		
Sundry/Others	180.00		
Total(w/o GST)	8,804.62		



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SLX 7631 P

<u>Materials</u>		<u>Cost (\$)</u>
1	Clip, eng room cover (x10)	20.00 / nec
2	Clips (x10)	30.00 / nec
3	Rivet, Fr bumper (x6)	30.00 / nec
Total		80.00
Less 23% discount		18.40
Total after discount		61.60
7% GST		4.31
Grand total		<u>\$ 65.91</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

Work Order: R001335
 License: SLX7631P
 Technician: ALNIV (108)
 Mileage: 74211
 Date: 1.2.21 18:21

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
-0°06'	-0°07'	-0°10' 0°50'
2°11'	2°10'	2°05' 3°05'
0°03'	0°01'	-0°02' 0°06'
13°47'	13°53'	11°15' 14°15'
13°40'	13°46'	11°05' 15°05'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°31'	0°31'	-0°10' 0°50'
3°02'	3°02'	2°05' 3°05'
0°04'	0°06'	-0°02' 0°06'
13°52'	13°53'	11°15' 14°15'
14°23'	14°23'	11°05' 15°05'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°37'*	-0°38'*	-0°30' 0°30'
-0°51'*	-0°52'*	-0°30' 0°30'
-0°05'	0°00'	
0°07'	0°07'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°54'	-0°54'	-1°15' 0°15'
0°05'	0°05'	0°02' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°24'	-0°24'	-1°15' 0°15'
0°05'	0°05'	0°02' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°30'	-0°30'	-0°30' 0°30'
0°11'	0°10'	0°04' 0°24'
0°00'	0°00'	

212-76318

off to work M/T-F
not unit to Base all the good
to go home

All DTCs

2021.02.01

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2017MY

All DTCs

2021.02.01

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name			Malfunction Condition
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs			
	Auto Stop & Go (AS&G)	ASG_25080000		No DTCs			
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs			
	AUTO CRUISE	GAS_0E640000		Non-target System			
	4WS/Electric Power Steering	EPS_45880040		No DTCs			
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs			
	SRS-AIR BAG	ORC_81047302		No DTCs			
	Air Conditioner	AC_80080011		No DTCs			
	ETACS	ETACS_83040801		No DTCs			
	Meter	MTR_84084001		No DTCs			
	Steering Angle Sensor	GS_SAS_47000100		Non-target System			
	AND	AND_8C080002		Non-equipped System or Communication Error			
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error			
	LIN	ETACS_83040801		Non-target System			
	Power Gate	ETG_92080000		No DTCs			

All DTCs

2021.02.01

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	KOS/IMMO/Keyless	KOS_8A880020		No DTCs		
	OSS	OSS_9588000B		No DTCs		
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
	ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
	Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
	Gateway	GW_C1000000		Non-equipped System or Communication Error		
	FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		