



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



GST Reg No : MR-8500111-X

ESTIMATE

Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV17791/Tong Ngiap Shiek Alec Reg No/Reg Date SLQ5652D / 14/07/201 Date In/Mileage / 0 Chassis No JMYSRCY1AGU006675 Engine No 4A92CP2588 Make/Model MIT/16MY LANCER EX 1.6 4AT (E21) Colour/Trim W03 WHITE SOLID / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/01/2021/ 17:03	QUC	442 / CocoLu	62194

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER LH REPAIR FRT FENDER RH, FRT DOOR LH	450 X 4			1800 2250.00
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR				100.00
M SUNDRY TOP UP AIRCON GAS				80.00
M SUNDRY FRT NUMBER PLATE WITH FRAME				50.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT, FRT FENDER RH & LH	350 X 6			2100 2450.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40.00
M SUNDRY Sundry				20.00
M FACE, FR BUMPER / OO	1.00	1040.00	23.00	800.80
M GARNISH, FR BUMPER, RH X NM	1.00	37.00	23.00	28.49
M GARNISH, FR BUMPER, LH X NM	1.00	37.00	23.00	28.49
M GRILLE, FR BUMPER / BR	1.00	78.00	23.00	60.06
M SUPPORT, FR BUMPER, RH / BR	1.00	13.00	23.00	10.01
M SUPPORT, FR BUMPER, LH / BR	1.00	13.00	23.00	10.01
M COVER, HEADLAMP SUPT PANEL	1.00	70.00	23.00	53.90
M BRACKET, FR BUMPER SIDE, RH CUT X NM	1.00	17.00	23.00	13.09
M BRACKET, FR BUMPER SIDE, LH X NM	1.00	17.00	23.00	13.09
M REINFORCEMENT, FR BUMPER	1.00	93.00	23.00	71.61
M COVER, FR BUMPER GRILLE / BT	1.00	5.00	23.00	3.85
M COVER, FR BUMPER GRILLE / MIS	1.00	5.00	23.00	3.85

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV17791/Tong Ngiap Shiek Alec Reg No/Reg Date SLQ5652D / 14/07/201 Date In/Mileage / 0 Chassis No JMYSRCY1AGU006675 Engine No 4A92CP2588 Make/Model MIT/16MY LANCER EX 1.6 4AT (E21) Colour/Trim W03 WHITE SOLID / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/01/2021/ 16:41	QUC	247 / DonBong	62194			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	COVER,ENG ROOM UNDER,FR	X NN			1.00	173.00	23.00	133.21
M	COVER,ENG ROOM SIDE,RH	X NN			1.00	88.00	23.00	67.76
M	COVER,ENG ROOM SIDE,LH	X NN			1.00	87.00	23.00	66.99
M	HOOD	X NN			1.00	913.00	23.00	703.01
M	LATCH,HOOD	X NN			1.00	58.00	23.00	44.66
M	BRACKET,FR FENDER,RH	X NN			1.00	16.00	23.00	12.32
M	BRACKET,FR FENDER,LH	X NN			1.00	16.00	23.00	12.32
M	FENDER,FR LH	X NN			1.00	688.00	23.00	529.76
M	PANEL,HEADLAMP SUPPORT,UPR	X NN			1.00	296.00	23.00	227.92
M	PNL,HEADLAMP SUPT,UPR RH	X NN			1.00	86.00	23.00	66.22
M	PNL,HEADLAMP SUPT,UPR LH	X NN			1.00	86.00	23.00	66.22
M	HEADLAMP ASSY,LH	X NN			1.00	846.00	23.00	651.42
M	HEADLAMP ASSY,RH	X NN			1.00	846.00	23.00	651.42
M	LAMP ASSY,FOG,FR RH	X NN			1.00	303.00	23.00	233.31
M	LAMP ASSY,FOG,FR LH	X NN			1.00	303.00	23.00	233.31
M	LAMP ASSY,SIDE MARKER,LH	X NN			1.00	607.00	23.00	467.39
M	LAMP ASSY,SIDE MARKER,RH	X NN			1.00	607.00	23.00	467.39
M	CONDENSER ASSY,A/C REFRIGE	X NN			1.00	1134.00	23.00	873.18
M	HOSE,A/C COMPR DISCHARGE	X NN			1.00	197.00	23.00	151.69
M	HOSE,A/C COMPR SUCTION	X NN			1.00	263.00	23.00	202.51
M	PIPE,A/C CONDENSER OUTLET	X NN			1.00	115.00	23.00	88.55
M	PIPE,RR A/C DISCHARGE	X NN			1.00	132.00	23.00	101.64
M	RADIATOR ASSY	X NN			1.00	1124.00	23.00	865.48
M	TANK ASSY,RADIATOR COMP	X NN			1.00	60.00	23.00	46.20
M	SHROUD,COOLING FAN	X NN			1.00	257.00	23.00	197.89
M	SHROUD,COOLING FAN	X NN			1.00	257.00	23.00	197.89
M	MOTOR,COOLING FAN(*)	X NN			1.00	467.00	23.00	359.59
M	CAP ASSY,RADIATOR	X NN			1.00	94.00	23.00	72.38
M	LLC 4L	X NN			1.00	26.00	23.00	20.02

Estimate

Steve CLKK)
22/1/20, 5.00pm
OO- NoL AL
EXCISE - ?
PIP
By BLBY
8 days

LKK Auto Consultants hence notify the Repairer of the following:

Confirm & accepted by _____

- To display as per page (s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett	12,592.77
7% GST on	881.49
Total Payable	13,474.26

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.