

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 01/4 11:15

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

MER-TP

6200

30/3/14 4/5 @ 6200 submit pass to idwan estimate. (Red @ 9261.32, 60%)
 01/4/21 @ 4.50pm revised to Alfred Toh via Meimen.



not submit
25/11/21
6 dpr
2/5
6200
90096608
Thyphie
please submit LOD to insurance.
Bifrost Auto Pte Ltd

Model : Mazda 2 5 Door Hatchback 1.5L
 Registraion No : SLZ 277 P
 Chassis No: JM6DJ2HAA01100286
 Year of Manufacturing: 2015

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875
 Tel: 65 64524457 / Fax: +65 64524584
 CO. Reg. No.: 201929175W

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Bumper	892.00	\$ 992.00 ✓
2	1	Rear Bumper Retainer (RHS)		\$ 18.25 - X
3	1	Rear Bumper Bracket (RHS)		\$ 15.30 - X
4	1	Rear Bumper Lower Lip		\$ 215.20 X
5	1	Rear Bumper Reinforcement		\$ 185.10 - X
6	1	Rear Fender (RHS)	1123.85	\$ 1123.85 ✓
7	1	Rear Fender Shield (RHS)	108.00	\$ 108.00 ✓
8	1	Rear Fender Inner Trim Board (RHS)		\$ 487.20 X
9	1	Rear Fender Arch (RHS)		\$ 215.40 - X
10	1	Rear Tail Lamp (RHS)		\$ 495.30 - X
11	1	Rear Tail Lamp Panel (RHS)		\$ 225.40 X
12	1	Rear Door (RHS)	1021.20	\$ 1021.20 ✓
13	1	Rear Door Inner Trim Board (RHS)	685.10	\$ 685.10 ✓
14	1	Rear Door Handle (RHS)		\$ 89.20 - X
15	1	Rear Door Weatherstrip (RHS)	151.30	\$ 151.30 ✓
16	1	Rear Door Outer Molding (RHS)	96.80	\$ 96.80 ✓
17	1	Rear Door Checker (RHS)		\$ 45.20 - X
18	1	Rear Door Upper Hinge (RHS)		\$ 81.20 - X
19	1	Rear Door Lower Hinge (RHS)		\$ 82.40 - X
20	1	Rear Door Lock (RHS)	285.30	\$ 285.30 ✓
21	1	Rear Door Lock Actuator (RHS)		\$ - - X
22	1	Rear Door Power Window Regulator (RHS)		\$ 286.50 - ✓
23	1	Rear Door Power Window Regulator Motor (RHS)		\$ 238.70 - ✓
24	1	Front Door (RHS)		\$ 985.80 - ✓
25	1	Side Rocker Panel (RHS)		\$ 765.20 X
26	1	Rear Absorber (RHS)		\$ 341.50 X
27	1	Rear Upper Arm (RHS)		\$ 341.80 - X
28	1	Rear Lower Arm (RHS)		\$ 375.70 X
29	1	Rear Control Arm (RHS)		\$ 216.30 X
30	1	Rear Knuckle Hub (RHS)		\$ 485.50 X
31	1	Rear Wheel Bearing (RHS)	292.00	\$ 292.00 ✓

\$ -
 -20% \$ -
 Total for spare parts \$ -

7-6186.55
 202
 4549.24

Special Nett

1	10	Rear Bumper Clip	net	\$	5.00	\$	50.00	✓
2	10	Rear Fender Shield Clip (RHS)	net	\$	5.00	\$	50.00	✓
3	4	Tail Lamp Clip (RHS)	net	\$	5.00	\$	20.00	X
4	1	Rear Sport Rim (RHS)	cut / net	\$	1,200.00	\$	1,200.00	500
5	1	Rear Wheel Tyre (RHS)	cut LP 200 602	\$	800.00	\$	800.00	120

Total for SP \$ 2,120.00
Sub-Total for Parts : \$ 2,120.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.	\$	1,500.00 250
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,800.00 900
3		Apply rust proofing on the adjacent panels	\$	80.00 80
4		To supply under coating / putty on parts replaced	\$	80.00 1.
5		To perform water seepage test after repair	\$	50.00 X
6		Check and re-adjust wheel alignment	\$	100.00 ✓
7		Reset engine management systm with diagnostic fault e.g. ABS,SRS, ECU memory etc	\$	200.00 X
8		Remove and reinstall cushions,seat, backrest, inner trim, garnish/or upholstery to facilitate repair	\$	120.00 80
9		Dismantle and transfer door fittings and mechanism to new door/facilitate repair	\$	80.00 ✓
10		Remove and refir bumper sensor	\$	60.00 50

TOTAL AMOUNT : \$ 4,070.00
OVERALL COST: \$ 6,190.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 4949.24
S/W- 720.00
L- 2140.00
7809.24
207
6247.

not about
Lhr
25/1/21
6 dy, 1/53
90096608
Bifrost Auto Pte Ltd
NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875
Tel: 65 64524457 / Fax: +65 64524584
CO. Reg. No.: 201929175W

Model : Mazda 2 5 Door Hatchback 1.5L
Registraion No : SLZ 277 P
Chassis No: JM6DJ2HAA01100286
Year of Manufacturing: 2015

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Bumper		\$ -
2	1	Rear Bumper Retainer (RHS)		\$ -
3	1	Rear Bumper Bracket (RHS)		\$ -
4	1	Rear Bumper Lower Lip		\$ -
5	1	Rear Bumper Reinforcement		\$ -
6	1	Rear Fender (RHS)		\$ -
7	1	Rear Fender Shield (RHS)		\$ -
8	1	Rear Fender Inner Trim Board (RHS)		\$ -
9	1	Rear Fender Arch (RHS)		\$ -
10	1	Rear Tail Lamp (RHS)		\$ -
11	1	Rear Tail Lamp Panel (RHS)		\$ -
12	1	Rear Door (RHS)		\$ -
13	1	Rear Door Inner Trim Board (RHS)		\$ -
14	1	Rear Door Handle (RHS)		\$ -
15	1	Rear Door Weatherstrip (RHS)		\$ -
16	1	Rear Door Outer Molding (RHS)		\$ -
17	1	Rear Door Checker (RHS)		\$ -
18	1	Rear Door Upper Hinge (RHS)		\$ -
19	1	Rear Door Lower Hinge (RHS)		\$ -
20	1	Rear Door Lock (RHS)		\$ -
21	1	Rear Door Lock Actuator (RHS)		\$ -
22	1	Rear Door Power Window Regulator (RHS)		\$ -
23	1	Rear Door Power Window Regulator Motor (RHS)		\$ -
24	1	Front Door (RHS)		\$ -
25	1	Side Rocker Panel (RHS)		\$ -
26	1	Rear Absorber (RHS)		\$ -
27	1	Rear Upper Arm (RHS)		\$ -
28	1	Rear Lower Arm (RHS)		\$ -
29	1	Rear Control Arm (RHS)		\$ -
30	1	Rear Knuckle Hub (RHS)		\$ -
31	1	Rear Wheel Bearing (RHS)		\$ -

\$ -
-20% \$ -
Total for spare parts \$ -

Special Nett

1	10	Rear Bumper Clip	100	\$	5.00	\$	50.00	✓
2	10	Rear Fender Shield Clip (RHS)	100	\$	5.00	\$	50.00	✓
3	4	Tail Lamp Clip (RHS)	10	\$	5.00	\$	20.00	X
4	1	Rear Sport Rim (RHS)	100/100	\$	1,200.00	\$	1,200.00	500
5	1	Rear Wheel Tyre (RHS)	100 LP 200 600	\$	800.00	\$	800.00	

Total for SP \$ 2,120.00

Sub-Total for Parts : \$ 2,120.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.	\$	1,500.00 850
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,800.00 900
3		Apply rust proofing on the adjacent panels	\$	80.00 80
4		To supply under coating / putty on parts replaced	\$	80.00 10
5		To perform water seepage test after repair	\$	50.00 X
6		Check and re-adjust wheel alignment	\$	100.00 ✓
7		Reset engine management systm with diagnostic fault e.g. ABS,SRS, ECU memory etc	\$	200.00 X
8		Remove and reinstall cushions,seat, backrest, inner trim, garnish/or upholstery to facilitate repair	\$	120.00 80
9		Dismantle and transfer door fittings and mechanism to new door/facilitate repair	\$	80.00 ✓
10		Remove and refir bumper sensor	\$	60.00 50

TOTAL AMOUNT : \$ 4,070.00

OVERALL COST: \$ 6,190.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: