

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Name: SB Express Logistics Pte Ltd
Address: c/o Blk 3006 Ubi Rd 1
#01-336 Singapore 408700
Date: 12-Jan-21
Vehicle No.: SLF51D
Model: Porsche Macan GTS PDK E5 SR

Items:

S/N	Description	Amount
1 pc	Tailgate	repair
1 pc	Tailgate "Macan GTS" emblem	188 \$ Xnn 430.00 xx
1 pc	Tailgate inner trim board	\$ 820.00 xx nn.
1 pc	End panel	\$ 3,670.00 x R
1 pc	End panel top garnish	435.65 \$ Xnn 720.00 xx
1 pc	Rear bumper	1102.10 \$ 3,150.00 de
2 pcs	Rear bumper retainer (\$220 x 2) @ 20 each	240 \$ 440.00 cur
1 pc	Rear bumper top garnish "Macan" chrome	494.40 \$ Xnn 730.00 xx
2 pc	Rear bumper reflector 112 A/L @ 67.65 each	135.30 \$ 320.00 aut
1 pc	Towing cover	146.02 \$ 250.00 de
1 pc	Rear bumper diffuser	965.89 \$ 2,250.00 de
1 pc	Rear bumper camera	\$ 830.00 x nn.
2 pcs	Number plate lamp (\$220 x 2) @ 90 each	180 \$ 440.00 dis
1 pc	Reinforcement panel	600 \$ 985.00 bf
2 / 4 pcs	Reverse sensor (\$230 x 4)	400 \$ 920.00 nn 460
1 pc	Weatherstrip in	\$ 15,955.00
1 pc	Centre bracket cur	204.05
1 pc	Centre bracket sensor cur	280.
Special Nett Items:		
1 set	Rear Bumper clips	\$ 40.00 30 each
1 set	End panel top garnish clip	\$ 50.00 x nn.
1 set	Number plate	\$ 45.00 40
1 set	Rear bumper diffuser clip	\$ 40.00 20 each
		\$ 175.00 90.
		Less 10% \$ 3,191.00 4553.87
		Total \$ 12,764.00 10,4098.48
		5671.92
		5104.72

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Labour

- | | | | | |
|----|---|----|--------|-------|
| 1) | To remove, refit, replaced damaged lamps and check up rear electrical wiring | \$ | 60.00 | 30. |
| 2) | To remove and refit reverse sensor | \$ | 120.00 | 30. |
| 3) | To apply undercoating on repaired and replaced panel | \$ | 150.00 | X 11. |
| | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damage consistent to the accident. (including all repair parts) | | | |
| 4) | | \$ | 800.00 | 550 |
| 5) | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | \$ | 800.00 | 700 |

Diagnostic - \$150

\$ 800.00
\$ 1,930.00

1260 1460

4098.48
90
1260
5448.48
454350
4 days *

* To check part price
Tanpin 97415747
WP 9/2/21 @ 1215
1/3 Resurvey after repair
tanpin@lkhant.com
8/5 days

5104.72
90
1460
6654.72
454350
0.4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: