



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ABDUL HALEEM BIN MOHAMED ALI	Cust No/Name KCV15310/ABDUL HALEEM BIN MOHAMED ALI
BLK 2 CHAI CHEE ROAD	Reg No/Reg Date SCW748U / 21/01/202
#03-280	Date In/Mileage / 0
SINGAPORE 461002	Chassis No GF7W0602178
Contact No	Engine No 4J11BM9998
	Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV15310	CRDVCH	25/01/2021/ 11:37	BLC	442 / CocoLu	62243			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1350.00
RENEW TAILGATE, REAR BUMPER, REPAIR REAR END PANEL					450 X 1			60.00
E PNT88000								240.00
REMOVE & INSTALL PARKING SENSOR								80.00
E PNT88000								40.00
REMOVE & INSTALL REAR WINDSCREEN								40.00
M SUNDRY								40.00
APPLY SEALANT FOR REAR WINDSCREEN								40.00
M SUNDRY								40.00
C&C LOGO								300.00
M SUNDRY								1225.00
APPLY SEALANT FOR ACCIDENT PORTION								875
E PNT88000								30.00
REMOVE & INSTALL TAILGATE TRIMS AND REAR COMPARTMENT TRIMS								120.00
E PNT98000								20.00
SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR END PANEL, REAR AIRDAM - 725					350 X 2.5			807.00
A 54900099								12.00
CHECK WIRING & ELECTRICAL SYSTEM								79.00
A 10028901								292.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								984.00
M SUNDRY								41.00
Sundry								6.00
M FACE, RR BUMPER					1.00	807.00	00.00	807.00
M BRKT, R/BMPR FACE SIDE, RH					1.00	12.00	00.00	12.00
M BRKT, R/BMPR FACE SIDE, LH					1.00	12.00	00.00	12.00
M REINFORCEMENT, RR BUMPER, LH					1.00	79.00	00.00	79.00
M REINFORCEMENT, RR BUMPER, RH					1.00	79.00	00.00	79.00
M EXTENSION, RR BUMPER					1.00	292.00	00.00	292.00
M PANEL ASSY, TAILGATE					1.00	984.00	00.00	984.00
M DAM, TAILGATE, LWR					1.00	41.00	00.00	41.00
M STOPPER, WINDSHIELD GLASS					2.00	3.00	00.00	6.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ABDUL HALEEM BIN MOHAMED ALI BLK 2 CHAI CHEE ROAD #03-280 SINGAPORE 461002 Contact No	Cust No/Name KCV15310/ABDUL HALEEM BIN MOHAMED ALI Reg No/Reg Date SCW748U / 21/01/202 Date In/Mileage / 0 Chassis No GF7W0602178 Engine No 4J11BM9998 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV15310	CRDVCH	25/01/2021/ 11:37	BLC	442 / CocoLu	62243			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
M	FASTENER,WINDSHIELD	✓ MC			4.00	6.00	00.00	24.00
M	DAM,TAILGATE SIDE	✓ MC			2.00	27.00	00.00	54.00
M	DAM,TAILGATE,UPR	✓ MC			1.00	13.00	00.00	13.00
M	W/STRIP,TAILGATE OPENING	X NN			1.00	213.00	00.00	213.00
M	LATCH,TAILGATE	X NN			1.00	475.00	00.00	475.00
M	TRIM,RR END	X NN			1.00	113.00	00.00	113.00
M	REFLECTOR,TAIL LAMP,LH	✓ CHT			1.00	100.00	00.00	100.00
M	LAMP ASSY,COMB,RR LH	✓ X NN			1.00	600.00	00.00	600.00
M	LAMP ASSY,TAIL,LH	X NN			1.00	506.00	00.00	506.00

Estimate

Steve (LKK) 25/1/21, 12.00pm

OD- Mt AL

EXCESS - ?

P/P

M BL SM
5 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Confirm & accepted by

8121.00

7% GST on Net 7,915.00 554.05
Total Payable 8,469.05

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.