

AIG

Vehicle number	SMK7273X
Make / Model	MITSUBISHI ATTRAGE
Chassis number	MMBSTA13AJH003958
Accident date	12/1/2021
Reference	2101-36

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	814.20 <i>de</i>
1	REAR BUMPER LOWER GARNISH	437.00 <i>X</i>
2	REAR BUMPER BRACKET	201.80 <i>LH-de RH-X</i>
2	REAR BUMPER RETAINER	69.00 <i>LH-de RH-X</i>
2	REAR BUMPER REFLECTOR	276.00 <i>LH-? RH-X</i>
1	END PANEL	807.30 <i>photo LH-? RH-X</i>
1	END PANEL TOP GARNISH	236.00 <i>?</i>
1	END PANEL KEYLESS SENSOR SPEAKER	138.00 <i>?</i>
1	KEYLESS SENSOR	172.50 <i>?</i>
2	TAILLAMP	862.00 <i>LH-con RH-X</i>
2	TAILLAMP PANEL	192.00 <i>LH-? RH-X</i>
2	TAILLAMP SEALER	72.00 <i>LH-con RH-X</i>
1	BOOTLID	952.20 <i>de</i>
1	BOOTLID LOCK	247.20 <i>?</i>
1	BOOTLID LOCK STRIKER	24.00 <i>X</i>
1	BOOTLID CHROME OUTER GARNISH	365.70 <i>?</i>
1	BOOTLID WEATHERSTRIP	170.20 <i>photo</i>
1	BOOTLID EMBLEM - ATTRAGE	25.30 <i>we</i>
1	BOOTLID EMBLEM - MIVEC	39.50 <i>we</i>
1	BOOTLID - LOGO	47.15 <i>we</i>
2	BOOTLID HINGE	441.60 <i>RP</i>
1	BOOTLID INNER TRIM	172.50 <i>X</i>
1	SPARE TYRE TOP BOARD	212.75 <i>de</i>
1	FLOOR PANEL	1410.20 <i>RP</i>
2	REAR FENDER	1662.90 <i>LH-bul RH-X</i>
1	REAR FENDER INNER TRIM	281.70 <i>? photo</i>
2	REAR FENDER AIR VENT	187.40 <i>de</i>
1	REAR WINDSCREEN MOUDLING	92.00 <i>we</i>
1	MUD FLAP	96.00 <i>X</i>
1	REAR AIRDUCT	67.20 <i>?</i>
1	REAR AIRDUCT COVER	91.20 <i>?</i>
		10864.50
Less 10%		1086.45
Subtotal		9778.05
Balance C/F		9778.05

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	9778.05
1 SET	REAR BUMPER CLIP	50.00 <i>30.00</i>
2 SET	REAR FENDER INNER TRIM CLIP	120.00 <i>30.00</i>
1 SET	BOOTLID INNER TRIM CLIP	60.00 X
1	REAR NUMBER PLATE	80.00 X
1	WINDSCREEN SEALANT	50.00 <i>40.00</i>
1 BOT	BRAKE FULID	60.00 X
1 SET	REVERSE SENSOR	500.00 <i>200.00</i>
1	REAR NUMBER PLATE GARNISH	60.00
1	END PANEL TOP GARNISH CLIP	60.00 <i>10.00</i>
	Subtotal	1040.00
	Balance C/F	10818.05
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	10818.05
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	120.00 <i>30</i>
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00 <i>60</i>
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 <i>30</i>
4	REMOVE AND REFIT FUEL TANK	300.00 <i>100? photo</i>
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 <i>120</i>
6	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 <i>60</i>
7	REMOVE AND RENEW FLOOR INSULATOR	120.00 X
8	PANEL BEATING ON AFFECTED AREAS	2400.00 <i>1000</i>
9	SPRAY PAINTING ON AFFECTED AREAS	2400.00 <i>1000</i>
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>40</i>
	Subtotal	6190.00
	Grand total	17008.05

Tanjin 97885449

'WP' 25/1/21 E 1345

c/s Resing after repair

Tanjin e 11hantoon

7days