

TO : INDIA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLG6804D
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 23.01.21
 TIME OF ACCIDENT : 19:00HRS

28	TAILGATE INNER SIDE TRIM	new	2	\$ 98.00	\$ 196.00	+
29	TAILGATE WEATHER STRIP	cut	1	\$ 168.40	\$ 168.40	✓
30	TAILGATE WINDSCREEN MOULDING (SET)	new	1	\$ 164.00	\$ 164.00	✓
31	BUZZER	cut	1	\$ 109.00	\$ 109.00	✓
32	REAR END PANEL	replaced	1	\$ 530.00	\$ 530.00	✓
33	REAR END PANEL TOP GARNISH	replaced	1	\$ 146.30	\$ 146.30	✓
34	REAR FLOOR PANEL	replaced	1	\$ 1,130.00	\$ 1,130.00	✓
35	REAR FLOOR BOTTOM CROSS PANEL	new	1	\$ 862.00	\$ 862.00	+
36	REAR FLOOR TOWING PANEL	new	1	\$ 545.00	\$ 545.00	+
37	REAR FLOOR SIDE PANEL RH	new	1	\$ 297.60	\$ 297.60	+
38	REAR FLOOR PANEL BOTTOM GARNISH	replaced	1	\$ 269.00	\$ 269.00	✓
39	REAR FLOOR PANEL TOP BOARD	replaced	1	\$ 300.40	\$ 300.40	✓
40	REAR STORAGE BOX	cut	1	\$ 495.00	\$ 495.00	282
41	REAR CHASSIS MEMBER RH	new	1	\$ 797.40	\$ 797.40	+
42	EDLC MODULE	new	1	\$ 1,440.00	\$ 1,440.00	X
43	CENTER EXHAUST GASKET (SET)	new	1	\$ 80.00	\$ 80.00	40
44	CENTER EXHAUST	Best	1	\$ 1,980.00	\$ 1,980.00	956
45	CENTER EXHAUST INSULATOR	new	1	\$ 180.00	\$ 180.00	+
46	REAR EXHAUST INSULATOR	cut	1	\$ 155.00	\$ 155.00	✓
47	REAR EXHAUST PIPE	Best	1	\$ 980.00	\$ 980.00	785
48	REAR EXHAUST MOUNTING	new	4	\$ 18.00	\$ 72.00	+
49	REAR EXHAUST GASKET (SET)	new	1	\$ 80.00	\$ 80.00	40

10419.80
833584

TOTAL PRICE \$ 21,924.10
 LESS 20% \$ 4,384.82
 SUB TOTAL PRICE \$ 17,539.28

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIPS (SET)	1	\$ 80.00	\$ 80.00	30
3	TAIL LAMP CLIP (SET)	1	\$ 60.00	\$ 60.00	+
4	TAILGATE OUTER GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00	10
5	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	40
6	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	40
7	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00	60
8	REAR FENDER COWLING CLIP (SET)	1	\$ 80.00	\$ 80.00	+
9	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00	20
10	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	60
11	REAR FLOOR PANEL SEALANT	1	\$ 350.00	\$ 350.00	60

TO : **INDIA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLG6804D**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 23.01.21
 TIME OF ACCIDENT : 19:00HRS

12	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) ^{NEW}	1	\$ 80.00	\$ 80.00	80
13	REVERSE SENSOR (SET) ^{Damaged}	1	\$ 220.00	\$ 220.00	200

550

TOTAL \$ 1,440.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	1300
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,200.00	1000
3	TUFF COAT	\$ 250.00	80
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	200
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	/
11	TRANSFER TAILGATE MECHANISM	\$ 80.00	/
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	160
13	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	/
14	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	X
15	FOUR WHEEL ALIGNMENT	\$ 120.00	X
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 7,200.00

3170

TO : **INDIA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLG6804D**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 23.01.21
TIME OF ACCIDENT : 19:00HRS

TOTAL PARTS COST : \$ 18,979.28
TOTAL LABOUR COST : \$ 7,200.00
TOTAL REPAIR COST : \$ 26,179.28

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE
SERVICE ADVISOR
MICHELLE
HP : 9856 4815

Adrian Lj
L/S 25/01/21
092yrs.

total : 12055.84
L/S : 9.6k. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: