



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21001157/Uqd3q2	
			Date: 05/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 9338S	Veh. Inspected	SKP 8415U
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100248/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	25/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 6 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JM6GJ1071F0145024	Colour	BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 ZR17	NEXEN	6 mm
	L/H Front Tyre	215/55 ZR17	NEXEN	6 mm
	R/H Rear Tyre	215/55 ZR17	NEXEN	6 mm
	L/H Rear Tyre	215/55 ZR17	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/01/2021	Inspection Date	26/01/2021
	Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	