

Repair Estimate

Alpha Car Services Pte Ltd

Blk C Kaki Bukit Ave 6 #01-59 Autobay@Kaki Bukit Singapore 417883

Office: (65) 6509 8258

UEN NO: 201717633Z

Make/Model: MAZDA 3

Engine/Chassis No.: JM6BN22A8H0165320


Date of accident: 22/01/2021

Damaged area: O/S

Date: 26/01/2021

Claim Type: TP

VRN: SLR 1316X



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	REAR BUMPER ASSY	1	\$ 1,082.00	\$ 1,082.00
2	REAR BUMPER REINFORCEMENT	1	\$ 332.00	\$ 332.00
3	REAR BUMPER TOW COVER	1	\$ 78.00	\$ 78.00
4	REAR BOOTLID ASSY	1	\$ 2,195.00	\$ 2,195.00
5	REAR BOOTLID NO PLATE LAMP	1	\$ 68.00	\$ 68.00
6	REAR BOOTLID LOCK MECHANISM	1	\$ 225.00	\$ 225.00
7	REAR END LOWER PANEL	1	\$ 1,187.00	\$ 1,187.00
8	REAR END LOWER PANEL TOP GARNISH	1	\$ 152.00	\$ 152.00
9	REAR EXHAUST MUFFLER ASSY	1	\$ 1,264.00	\$ 1,264.00
10	REAR EXHAUST MUFFLER RUBBER MOUNTING	2	\$ 38.00	\$ 38.00
Subtotal				\$ 6,621.00
List discount				20%
Total				\$ 5,296.80

de✓ 997.50
bt✓
X nn
bt✓ 1185.20
X nn
bt✓
R x
de✓
X nn
X nn
2891.70
2313.36

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	REAR BOOTLID CENTER LOGO	1	\$ 106.00	\$ 106.00
2	REAR BOOTLID "MAZDA 3" EMBLEM	1	\$ 104.00	\$ 104.00
3	REAR BOOTLID "SKYACTIVE" EMBLEM	1	\$ 106.00	\$ 106.00
4	REAR BUMPER CLIPS	10	\$ 50.00	\$ 500.00
5	REAR END LOWER PANEL TOP GARNISH CLIP	6	\$ 30.00	\$ 180.00
6	REAR END LOWER PANEL SEALANT	1	\$ 120.00	\$ 120.00
7	REAR BUMPER REVERSE SENSOR	2	\$ 250.00	\$ 500.00
8	REAR NO PLATE WITH GARNISH	1	\$ 80.00	\$ 80.00
9				
Total				\$ 846.00

465

Repair Estimate

Labour			
No.	Description		Amount
1	LABOUR FOR PANEL BEATING,CUT,WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	\$	1,000.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	\$	1,000.00
3	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	\$	120.00
4	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM	\$	80.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	\$	150.00
6	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	\$	80.00
7	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	\$	100.00
Total labour		\$	2,530.00
Estimate Grand Total		\$	8,672.80

600.700

600.700

30.

60.

60.

30.

X nn.

1380

1580

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749.

WP 26/1/21 @ 11am

Lumpsum

Resurvey after repair

Taufik e lkhanku-wm

5 days.

~~2313.56~~

~~465~~

~~1380~~

~~4358.36~~

4583300

5 days #

2313.56

465

1580

4358.36

4583500

5 days