



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SRI RAM KJ	Cust No/Name LCV11855/SRI RAM KJ
BLK 230 BUKIT BATOK EAST AVENUE	Reg No/Reg Date SMR5296G / 13/01/202
#09-224	Date In/Mileage / 0
SINGAPORE 650230	Chassis No KNAF3416ML5065293
Contact No	Engine No G4FGKH753055
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV11855	CRDVCH	25/01/2021/ 12:48		442 / Cocolu	27971			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								400.00
RENEW FRT DOOR RH, WINDMIRROR RH								120 180.00
E PNT88000								580 720.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT98000								40.00
SPRAY PAINT FOR FRT DOOR RH, WINDMIRROR RH 100								30.00
M SUNDRY								120.00
APPLY SEALANT FOR ACCIDENT PORTION								20.00
A 90000001								
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
Sundry								
M PANEL ASSY-FRONT DOOR, RH					1.00	1277.00	00.00	1277.00
M HINGE ASSY-FRONT DOOR, RH					1.00	30.00	00.00	30.00
M HINGE ASSY-DOOR LOWER, RH					1.00	27.00	00.00	27.00
M BLACK TAPE-FR DR RR, RH					1.00	13.00	00.00	13.00
M MIRROR ASSY-OUTSIDE RR VIEW, RH					1.00	559.00	00.00	559.00
M MOTOR ASSY-FRONT POWER WDW, RH					1.00	362.00	00.00	362.00
M PANEL ASSY-FRONT DR MODULE, RH					1.00	241.00	00.00	241.00
M MOULDING ASSY-FRT DR FRAME, RH					1.00	37.00	00.00	37.00

480 + 100 = 580 (CRS cal/m)

Estimate

Estimate

Steve (LKK) 25/1/21, 2.00pm

00 AM A/L

EXPRESS - ?

P/P

By BL sy

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm & accepted by subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

7% GST on **Nett** 4,056.00 **283.92**

Total Payable 4,339.92

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.