

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SLU 20 P**
Model : **BMW M235i**
Year : _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 1,147.35	\$ 1,147.35
2	Bootlid logo	1	\$ 71.50	\$ 71.50
3	Bootlid emblem 'M'	1	\$ 81.75	\$ 81.75
4	Bootlid emblem '235i'	1	\$ 82.75	\$ 82.75
5	Bootlid inner trim board	1	\$ 156.10	\$ 156.10
6	Bootlid lock mechanism	1	\$ 186.40	\$ 186.40
7	Bootlid weatherstrip	1	\$ 126.80	\$ 126.80
8	Rear bumper	1	\$ 1,029.75	\$ 1,029.75
9	Rear bumper diffuser (carbon fibre)	1	\$ 1,332.60	\$ 1,332.60
10	Rear bumper side retainer	2	\$ 56.10	\$ 112.20
11	Rear bumper inner sponge	1	\$ 61.65	\$ 61.65
12	Rear bumper reinforcement	1	\$ 418.60	\$ 418.60
13	Rear bumper reinforcement bracket	2	\$ 120.00	\$ 240.00
14	Rear bumper bracket	2	\$ 61.66	\$ 123.31
15	Rear bumper reflector	1	\$ 37.30	\$ 37.30
16	Rear bumper tow cap	1	\$ 39.95	\$ 39.95
17	Rear bumper centre beam	1	\$ 383.00	\$ 383.00
18	Rear bumper under cover	1	\$ 50.45	\$ 50.45
19	Rear bumper reverse sensor	3	\$ 239.25	\$ 717.75
20	Rear end panel	1	\$ 507.45	\$ 507.45
21	Rear end panel top garnish	1	\$ 117.45	\$ 117.45
22	Taillamp	2	\$ 405.85	\$ 811.70
23	Taillmp garnish	2	\$ 44.95	\$ 89.90
24	Rear exhaust	1	\$ 1,451.35	\$ 1,451.35
25	Rear exhaust mounting	2	\$ 31.45	\$ 62.90
26	Rear exhaust head shield	1	\$ 66.35	\$ 66.35
27	Rear air vent	1	\$ 32.15	\$ 32.15
Parts Sub Total :				\$ 9,837.41
5% Discount				\$ 491.87
PARTS TOTAL :				\$ 9,345.54

3173.85
@ 5% 158.69
3015.16

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Bootlid sealant	1	\$ 100.00	\$ 100.00	NNX
3	Bootlid spoiler (carbon fibre)	1	\$ 1,800.00	\$ 1,800.00	cut ✓
4	Bootlid spoiler 'M PERFORMANCE' (carbon fibre) * provide invoice	1	\$ 5,900.00	\$ 5,900.00	cut ✓ 1000
5	Bootlid inner trim board clips	1	\$ 60.00	\$ 60.00	NNX
6	Rear bumper clips	1	\$ 60.00	\$ 60.00	NECV
7	Rear bumper diffuser (carbon fibre) after market item	1	\$ 2,400.00	\$ 2,400.00	DD ✓
8	Rear bumper diffuser clips	1	\$ 60.00	\$ 60.00	NECV
9	Rear bumper under cover clips	1	\$ 60.00	\$ 60.00	NNX
10	Rear bumper reverse sensor seal	3	\$ 60.00	\$ 180.00	NECV
11	Rear end panel sealant	1	\$ 100.00	\$ 100.00	NNX
12	Rear end panel top garnish clips	1	\$ 60.00	\$ 60.00	} NNX
13	Taillamp clips	2	\$ 60.00	\$ 120.00	
14	Taillamp seal	2	\$ 100.00	\$ 200.00	
SPECIAL NETT TOTAL :				\$ 11,240.00	

9489.38

Nos.	LABOUR	S\$	
1	R&R bootlid component	\$ 150.00	NNX
2	R&R reverse sensor	\$ 60.00	✓
3	Check wiring	\$ 120.00	✓
4	Diagnostic reset fault code	\$ 120.00	✓
5	Conduct water leak test	\$ 180.00	NNX
6	Upholstery	\$ 300.00	NNX
7	Panel beat	\$ 600.00	✓
8	Rust proofing	\$ 200.00	NNX
9	Spray paint	\$ 400.00	✓
LABOUR TOTAL :		\$ 4,600.00	

1220.00

PARTS TOTAL : \$ 9,345.54
SPECIAL NETT TOTAL : \$ 11,240.00
LABOUR TOTAL : \$ 4,600.00
GRAND TOTAL : \$ 25,185.54

Survey 27/1/2021 1145 hrs
Resurvey 28/1/2021 1145 hrs
lm lm

Lump sum repair
Repair Days 4

PARTS 3015.16
SN 9489.38
LABOUR 1220.00
13,724.54
@20% 2744.91
10979.63

L/S 10,950/2

TGlin
lm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: