

Lion City Rentals Pte Ltd
 CARROS CENTER
 60 JALAN LAM HUAT #04-01 S(737869)
 Main +65 62524991

Ms AIG Asi Pacific Pte Ltd
 Date: 25/01/2021
 Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLF2956E
 CHASSIS NO : NSP1707034026
 MAKE / MODEL : Toyota Sienta 1.5 x Auto
 DATE OF ACCIDENT : 13/07/2019
 YOUR INSURED VEHICLE NUMBER : SGL8813Y
 MILEAGE : 274649 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/R door SCR / CR4	1PC	\$ 1,404.00	\$ 1,404.00
2	R/R fender rubber pad / SCR	1PC	\$ 280.00	\$ 280.00
3	R/R door rubber pad / SCR	1PC	\$ 390.00	\$ 390.00
			LIST TOTAL S\$:	\$ 2,074.00
			25.00% DISCOUNT S\$:	\$ 518.50
				\$ 1,555.50

<u>LABOUR CHARGES</u>		
1	To labour charge for removing F/L door, R/R door, rear bumper out to facilitate replacement of parts. Also repair R/L fender	\$ 900.00 500
2	To respray rear bumper, F/L door, R/R door and R/R fender	\$ 1,200.00 600
3	Transfer tailgate mechanism	\$ 100.00 X
4	To configure keyless network security system back to factory specification	\$ 300.00 X
	LABOUR TOTAL S\$:	\$ 2,500.00
	TOTAL S\$:	\$ 4,055.50
	7% GST	\$ 283.89
	GRAND TOTAL S\$:	\$ 4,339.39

Repair day - 3 days

LIS
 After paint photo
 Sun Pin (LKK)
 26/01/2021
 TP without prejudice