



CYCLE & CARRIAGE

AIG - OD (REVERT)
SURVEY: 25/01/21
LKK - STEVE

VEHICLE NO : SMQ3505Y

MODEL : KIA/CERATO 1.6 A EX

WIP : 28010

Material	:	\$	<u>4,844.00</u>
Labour	:	\$	<u>5,185.00</u>
Sub-Total	:	\$	<u>10,029.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>10,029.00</u>
GST 7%	:	\$	<u>702.03</u>
Grand Total	:	\$	<u>10,731.03</u>
Finalise By/Date	:	<u>LARRY ON 09/03/21</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 11 WORKING DAYS + 4 days (2 weekends)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 27/01/2021	Cust No/Name	LCV11477/Mr Chew Yong Han Melvin
	Reg No/Reg Date	SMQ3505Y / 12/11/2019
	Date In/Mileage	26/01/2021/ 19335
	Chassis/Package	KNAF3416MK5052160 /KC17P
	Engine No	G4FGKH748635
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	09/03/2021/ 09:38	BLK	884 / Lauro Songcuan	28010

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BOOT, REAR LH FENDER & AFFECTED AREAS				1600.00 ✓
E PNT98000 SPRAY PAINT ON REAR BUMPER, REAR LH FENDER & BOOT				1050.00 ✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				120.00 ✓
E PNT88000 REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR				120.00 ✓
A 13900099 REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR				400.00 ✓
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS				240.00 ✓
M SUNDRY APPLY REAR WINDSCREEN SEALANT				80.00 ✓
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUPPLY C&C BADGE				40.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
E PNT88000 RENEW REAR END PANEL & LH TAIL LAMP HOUSING → <i>Supp</i>				800.00 X
E PNT98000 SPRAY PAINT REAR END PANEL & LH TAIL LAMP HOUSING → <i>Supp.</i>				525.00 X
X LAMP ASSY-REAR COMB INSIDE,LH ✓	1.00	608.00	20.00	486.40 ✓
X LAMP ASSY-REAR COMB OUTSIDE,LH ✓	1.00	675.00	20.00	540.00 ✓
X PANEL ASSY-TRUNK LID ✓	1.00	1297.00	20.00	1037.60 ✓
X PANEL ASSY-BACK ?	1.00	324.00	20.00	259.20 ?

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
 PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 27/01/2021	Cust No/Name	LCV11477/Mr Chew Yong Han Melvin
	Reg No/Reg Date	SMQ3505Y / 12/11/2019
	Date In/Mileage	26/01/2021/ 19335
	Chassis/Package	KNAF3416MK5052160 /KC17P
	Engine No	G4FGKH748635
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	09/03/2021/ 09:38	BLK	884 / Lauro Songcuan	28010


Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X PANEL ASSY-QUARTER OUTER,LH ✓	1.00	1349.00	20.00	1079.20
X PANEL ASSY-RR COMB LAMP HSG,LH ?	1.00	139.00	20.00	111.20
X LOGO ASSY-KIA SUB ✓	1.00	32.00	20.00	25.60
X EMBLEM-CERATO ✓	1.00	28.00	20.00	22.40
X COVER-RR BUMPER ✓	1.00	651.00	20.00	520.80
X COVER-RR BUMPER LWR ✓	1.00	241.00	20.00	192.80
X COVER-RR BUMPER FOG LAMP,LH ?	1.00	19.00	20.00	15.20
X LAMP ASSY-SIDE T/SIGNAL,LH ?	1.00	181.00	20.00	144.80
X BRACKET ASSY-RR BPR SIDE UPR,L ?	1.00	25.00	20.00	20.00
X FILM-ANTI CHIPPG LH ✓	1.00	27.00	20.00	21.60
X EXTN WIRING ASSY-BWS	1.00	207.00	20.00	165.60
X GLASS & MOULDING ASSY-QUARTER	1.00	252.00	20.00	201.60

TEXT
 AIG OD CLAIM - REVERT
 DOA: 25.01.2021
 SURVEY: STEVE (LKK) 25/01/2021
 11 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,844.00	Nett	10,029.00
Labour	5,005.00	7% GST on	702.03
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	10,731.03
Sundry/Others	180.00		
Total(w/o GST)	10,029.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMQ 3505 Y

<u>Materials</u>		<u>Cost \$</u>
1	Extn Wiring Assy- BWS	207.00 ✓ BR
2	Glass & Moulding Assy- Quarter	252.00 ✓ nec
		<u>459.00</u>
	20% Discount	91.80
		<u>367.20</u>
<u>Labour</u>		
1	Renew Rear End Panel & LH Tail Lamp Housing	800.00 ✓
2	Spray Paint Rear End Panel & Tail Lamp Housing	525.00 ✓
		<u>1,325.00</u>
	Labour & Materials	1,692.20
	7% GST	118.45
	Total	<u>1,810.65</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMQ 3505Y

WIP: 28010

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	COVER FOR BPC FOR LAMP-LH	? / SUPP		✓ BR	} Steve 29/1/91
2	LAMP ASSY-SIDE T/SIGNAL, LH	? / SUPP		✓ BR	
3	BRACKET ASSY-RR FOR SIDE VAC LH	? / SUPP		✓ BR	
4	Panel ASSY-RACE	? / SUPP		✓ OT	
5	Panel ASSY-RR COMB LAMP BSB-LH	? / SUPP		✓ TN	
6	EXTN WIRING ASSY-BWS	? / SUPP		✓ RC	
7	GLASS & MODING ASSY-GUARDER FIXED-LH	? / SUPP			
8	RENEW REAR END PANEL,	? / SUPP			
9	LH TAILAMP HOUSING - \$800/-	? / SUPP			
10	PAINTWORK REAR END PANEL,	? / SUPP			
11	LH TAILAMP HOUSING \$525	? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15	Total 11 days (+3 day)	? / SUPP		✓	
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	3/2/91	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Cerato 1.6

SURVEYOR: Steve Wk

Before

Fault Code Searching

Rescan Erase All DTC Go to DTC Save

ICU
 CLU
 IBU-SMK
 9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good


System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0238	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0179	OS Ver.	Android 10

After

Fault Code Searching

Rescan Erase All DTC Go to DTC Save



System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good


System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0238	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0179	OS Ver.	Android 10

APP

Fault Code Searching

Rescan Erase All DTC Go to DTC Save



System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0238	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0179	OS Ver.	Android 10