



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11477/CHEW YONG HAN MELVIN (ZHOU YONG
	Reg No/Reg Date	SMQ3505Y / 12/11/201
	Date In/Mileage	26/01/2021/ 0
	Chassis No	KNAF3416MK5052160
	Engine No	G4FGKH748635
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 13:48	QUK	282 / Kevin Leong	28010			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
REPLACE REAR BUMPER, BOOT, REAR LH FENDER & AFFECTED AREA								
E PNT98000								1050.00
PAINT WORK ON REAR BUMPER, REAR LH FENDER & BOOT								
E PNT88000								120.00
REMOVE & INSTALL REAR PARKING ASSIST								
E PNT88000								120.00
REMOVE & INSTALL BOOT COMPARTMENT FOR FACILITATE								
E PNT88000								120.00
REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR								
A 13900099								400.00
REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR								
E PNT88000								240.00
REMOVE & INSTALL REAR WINDSCREEN GLASS								
M SUNDRY								80.00
TO APPLY WINDSCREEN SEALANT								
M SUNDRY								80.00
TO APPLY BODY SEALANT ON AFFECTED AREA								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								50.00
TO SUPPLY C & C EMBLEM								
M SUNDRY								50.00
SUNDRIES								
M LAMP ASSY-REAR COMB INSIDE,LH					1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE,LH					1.00	675.00	20.00	540.00
M LAMP ASSY-CENTER GARNISH					1.00	690.00	20.00	552.00
M PANEL ASSY-TRUNK LID					1.00	1297.00	20.00	1037.60
M HINGE ASSY-TRUNK LID,LH					1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID,RH					1.00	97.00	20.00	77.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11477/CHEW YONG HAN MELVIN (ZHOU YONG
	Reg No/Reg Date	SMQ3505Y / 12/11/201
	Date In/Mileage	26/01/2021/ 0
	Chassis No	KNAF3416MK5052160
	Engine No	G4FGKH748635
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	25/01/2021/ 13:48	QUK	282 / Kevin Leong	28010
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
M PANEL ASSY-BACK	1.00	324.00	20.00	259.20	
M PANEL ASSY-QUARTER OUTER,LH	1.00	1349.00	20.00	1079.20	
M PANEL ASSY-RR COMB LAMP HSG,LH	1.00	139.00	20.00	111.20	
M TRIM ASSY-RR TRANSVERSE	1.00	41.00	20.00	32.80	
M GLASS ASSY-REAR WINDOW	1.00	447.00	20.00	357.60	
M LOGO ASSY-KIA SUB	1.00	32.00	20.00	25.60	
M EMBLEM-CERATO	1.00	28.00	20.00	22.40	
M COVER-RR BUMPER	1.00	651.00	20.00	520.80	
M COVER-RR BUMPER LWR	5.00	241.00	20.00	964.00	
M COVER-RR BUMPER UNDER,LH	1.00	33.00	20.00	26.40	
M COVER-RR BUMPER FOG LAMP,LH	1.00	19.00	20.00	15.20	
M LAMP ASSY-SIDE T/SIGNAL,LH	1.00	181.00	20.00	144.80	
M BRACKET-RR BEAM UPR MTG,LH	1.00	9.00	20.00	7.20	
M BRACKET-RR BEAM UPR MTG,RH	1.00	9.00	20.00	7.20	
M BRACKET-RR BEAM LWR,CTR	1.00	6.00	20.00	4.80	
M BRACKET-RR BEAM LWR MTG	1.00	6.00	20.00	4.80	
M BEAM-RR BUMPER	1.00	318.00	20.00	254.40	
M ANTENNA ASSY-SMARTKEY	1.00	46.00	20.00	36.80	
M STAY-RR BUMPER LH	1.00	65.00	20.00	52.00	
M STAY-RR BUMPER RH	1.00	65.00	20.00	52.00	
M BRACKET ASSY-RR BPR SIDE UPR,L	1.00	25.00	20.00	20.00	
M BRACKET-ASSY RR BPR SIDE UPR,R	1.00	31.00	20.00	24.80	
M FILM-ANTI CHIPPG LH	1.00	27.00	20.00	21.60	

Estimate

Confirm & accepted by

	Nett	11,276.00
	7% GST on	11276.00
		789.32
	Total Payable	12,065.32

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.