



AIG - TP CLAIM
SURVEY: 24/03/21
LKK - STEVE

VEHICLE NO : SLX5323S

MODEL : MIT/ATTRAGE 1.2 CVT

WIP : 62223

Material	:	\$	<u>1,290.49</u>
Labour	:	\$	<u>3,060.00</u>
Sub-Total	:	\$	<u>4,350.49</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>4,350.49</u>
GST 7%	:	\$	<u>304.53</u>
Grand Total	:	\$	<u>4,655.02</u>
Finalise By/Date :	<u>Larry on 01/04/21</u>		

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 06 WORKING DAYS + 2 days (wk. end)

* TP VEHICLE NO: SLX8626Z

* GIA search fee \$2.00

* claim loss of RENTAL

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 24/03/2021	<table> <tr> <td>Cust No/Name</td><td>/Mohd Ikbar S/O Mohd Ibrahim</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLX5323S / 29/03/2018</td></tr> <tr> <td>Date In/Mileage</td><td>24/03/2021/ 36786</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AJH002035</td></tr> <tr> <td>Engine No</td><td>3A92UGT7931</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>U01 TITANIUM GREY M/ BK BLACK</td></tr> </table>	Cust No/Name	/Mohd Ikbar S/O Mohd Ibrahim	Reg No/Reg Date	SLX5323S / 29/03/2018	Date In/Mileage	24/03/2021/ 36786	Chassis/Package	MMBSTA13AJH002035	Engine No	3A92UGT7931	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK
Cust No/Name	/Mohd Ikbar S/O Mohd Ibrahim														
Reg No/Reg Date	SLX5323S / 29/03/2018														
Date In/Mileage	24/03/2021/ 36786														
Chassis/Package	MMBSTA13AJH002035														
Engine No	3A92UGT7931														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	U01 TITANIUM GREY M/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	01/04/2021/ 09:33	TLC	884 / Lauro Songcuan	62223
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW REAR BUMPER, BOOTLID				900.00 ✓
E PNT88000	REMOVE & INSTALL PARKING SENSOR				60.00 ✓
E PNT98000	SPRAY PAINT FOR REAR BUMPER, BOOTLID				700.00 ✓
M SUNDRY	APPLY SEALANT FOR AFFECTED PORTIONS				40.00 ✓
M SUNDRY	SUPPLY C&C LOGO				40.00 ✓
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY	SUNDRIES				20.00 ✓
PNT88000	REPAIR REAR END PANEL & REAR RH FENDER → <i>supp</i>				450.00 X
PNT98000	SPRAY PAINT REAR END PANEL & REAR RH FENDER → <i>supp</i>				700.00 X
X	FACE,RR BUMPER ✓	748.00	1.00	* 751.00 23.00	578.27 ✓
X	PANEL,TRUNK LID X R	791.00	1.00	* 795.00 23.00	612.15 ?
X	MARK,THREE-DIA ✓	69.00	1.00	* 70.00 23.00	53.90 ✓
X	MARK,ATTRAGE ✓		1.00	21.00 23.00	16.17 ✓
X	EMBLEM MIVEC TECHNOLOGY → <i>supp</i>		1.00	30.00 00.00	30.00 X
Z TEXT	TP CLAIM AIG - SLX8626Z DOA: 22/01/2021 SURVEY: STEVE (LKK) 24/03/2021 06 DAYS				
* change price					
Guarantee Your Warranty, Maintain with Cycle & Carriage!					

Parts	1,290.49	Nett	4,350.49
Labour	2,960.00	7% GST on	304.53
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	4,655.02
Sundry/Others	100.00		
Total(w/o GST)	4,350.49		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SLX 5323 S

	<u>Materials</u>	<u>Cost \$</u>
1	Emblem Mivec Technology	30.00 /nec
	<u>Labour</u>	
1	Repair Rear End Panel & Rear RH Fender	450.00 /
2	Spray Paint Rear End Panel & Rear RH Fender	700.00 /
		<u>1,180.00</u>
	7% GST	82.60
	Total	<u>1,262.60</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: 5X 53235WIP: 62223

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Logo MIVEC	? / SUPP			
2		? / SUPP			
3	✓ Repair Rear End Panel } \$450	? / SUPP			
4	✓ Repair Rear RH Fender } \$250	? / SUPP			
5	✓ Respray Rear End Panel & Rear RH Fender	? / SUPP	\$700		Steve 25/3/21
6	✓ Repair Working Day 2 ✓	? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: atragrSURVEYOR: Steve Hk

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW20121-00
V.C.I. Version		B179
Vehicle Information		A13A 2018MY

Ref No. 812C.53333

Save to Log out

Dynamic check all the good

to Log out Dynamic check all the good

to Log out Dynamic check all the good

to Log out Dynamic check all the good

to Log out Dynamic check all the good

to Log out Dynamic check all the good

2021.03.29

