



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
Mohd Ikbar S/o Mohd Ibrahim Blk 389 Bukit Batok West Avenue #10-394 Singapore 650389 Contact No Mobile: 93627163	Cust No/Name /Mohd Ikbar S/O Mohd Ibrahim Reg No/Reg Date SLX5323S / 29/03/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH002035 Engine No 3A92UGT7931 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	23/01/2021/ 13:05		442 / CocoLu	62223

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, BOOTLID, REAR END PANEL 450 X 2				900 3200.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL 350 X 2				700 2200.00
M SUNDRY SUPPLY PARKING SENSOR				1 220.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40 80.00
M SUNDRY C&C LOGO				40.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120 280.00
M SUNDRY Sundry				20.00
M FACE,RR BUMPER	1.00	748.00	00.00	748.00
M BRACKET,RR BUMPER,RH	1.00	28.00	00.00	28.00
M BRACKET,RR BUMPER,LH	1.00	28.00	00.00	28.00
M PANEL,RR END	1.00	425.00	00.00	425.00
M LATCH,TRUNK LID	1.00	218.00	00.00	218.00
M WEATHERSTRIP,TRUNK LID	1.00	157.00	00.00	157.00
M PANEL,TRUNK LID	1.00	791.00	00.00	791.00
M MARK,THREE-DIA	1.00	69.00	00.00	69.00
M MARK,ATTRAGE	1.00	21.00	00.00	21.00
M TRIM,RR END	1.00	66.00	00.00	66.00
M BUZZER,KEYLESS OPERATIO,RR	1.00	91.00	00.00	91.00
M ANT,KEYLESS OPERATION,RR	1.00	96.00	00.00	96.00
M COVER,RR VENTILATOR	1.00	40.00	00.00	40.00

Estimate

24/3/21, 2.30pm
Steve CLKK)
W/L Pr
4 days

Confirm & accepted by

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

P/P

My Belong

Nett	8,908.00
7% GST on	623.56
Total Payable	9,531.56

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.