



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

LE & CARRIAGE

Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address

Mohd Ikbar S/o Mohd Ibrahim
Blk 389 Bukit Batok West Avenue
#10-394
Singapore 650389
Contact No Mobile: 93627163

Owner Name & Vehicle Info

Cust No/Name /Mohd Ikbar S/O Mohd Ibrahim
Reg No/Reg Date SLX53235 / 29/03/201
Date In/Mileage / 0
Chassis No MMBSTA13AJH002035
Engine No 3A92UGT7931
Make/Model MIT/18MY ATTRAGE 1.2 CVT
Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	23/01/2021/ 13:05		442 / Cocolu	62223

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, BOOTLID, REAR END PANEL 450 X 2	900			3200.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR	700			60.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL 350 X 2	220.00			
M SUNDRY SUPPLY PARKING SENSOR	220.00			
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION	40			80.00
M SUNDRY C&C LOGO				40.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	120			280.00
M SUNDRY Sundry				20.00
M FACE, RR BUMPER / 00	1.00	751	748.00	00.00
M BRACKET, RR BUMPER, RH 1 X NM	1.00		28.00	00.00
M BRACKET, RR BUMPER, LH 1 X NM	1.00		28.00	00.00
M PANEL, RR END 1 X NM	1.00		425.00	00.00
M LATCH, TRUNK LID X NM	1.00		218.00	00.00
M WEATHERSTRIP, TRUNK LID X NM	1.00		218.00	00.00
M PANEL, TRUNK LID 1 X NM	1.00		157.00	00.00
M MARK, THREE-DIA 1 X NM	1.00	795	791.00	00.00
M MARK, ATTRAGE 1 X NM	1.00	70	69.00	00.00
M TRIM, RR END 1 X NM	1.00		21.00	00.00
M BUZZER, KEYLESS OPERATION, RR 1 X NM	1.00		66.00	00.00
M ANT, KEYLESS OPERATION, RR 1 X NM	1.00		91.00	00.00
M COVER, RR VENTILATOR 1 X NM	1.00		96.00	00.00
	1.00		40.00	00.00

Estimate

24/3/21, 2.30pm
Steve CLKK)
Wil Pri
6 days

Confirm & accepted by

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

P/P

My Bil sy

7% GST on 8908.00
Total Payable 9,531.56

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.