

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD777B**AAD2101-097***Not Authored**1/1/2021*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 JAN 2021**SHD777B**

VF1ABL15AUC283310

RENAULT

LATITUDE

20/01/2021

CHINA

31/08/2016

PART		LIST	
1	DOOR PANEL FRT RH	\$ 2,844.66	✓
1	DOOR WEATHERSTRIP FRT RH	\$ 410.27	?
1	DOOR HANDLE OUTER FRT RH	\$ 477.76	X
1	DOOR HANDLE MODULE FRT RH	\$ 133.60	X
1	DOOR REGULATOR FRT RH	\$ 505.19	—
1	DOOR REGULATOR MOTOR FRT RH	\$ 796.46	—
1	DOOR HINGE UPPER FRT RH	\$ 261.28	X
1	DOOR HINGE LOWER FRT RH	\$ 300.55	^
1	CENTRE PILLAR OUTER	\$ 880.14	✓
1	CENTER PILLAR INNER	\$ 907.76	?
1	DOOR PANEL REAR RH	\$ 2,844.66	✓
1	DOOR WEATHERSTRIP REAR RH	\$ 311.60	50% ✓
1	DOOR REGULATOR REAR RH	\$ 450.60	?
1	DOOR REGULATOR MOTOR REAR RH	\$ 758.10	?
1	DOOR HINGE UPPER REAR RH	\$ 241.60	?
1	DOOR HINGE LOWER REAR RH	\$ 169.90	✓
1	DOOR MIRROR ASSY RH	\$ 1,483.40	X
1	FENDER PANEL FRT RH	\$ 437.10	X
1	ROCKER PANEL OUTER RH	\$ 1,184.99	✓
TOTAL		\$ 15,399.61	
10%		\$ 1,539.96	
		\$ 13,859.65	

Special Nett

1	DOOR TRIM CLIP	\$ 70.00	X
1	DOOR SEAL CLIP	\$ 65.00	X
1	DOOR MOULDING CLIP	\$ 70.00	X

Trans-cab Auto Services Pte Ltd**AAD2101-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD777B

1 DOOR STICKER TRANSCAB	\$	100.00	601n
1 DOOR STICKER 65553333	\$	100.00	601n
1 DOOR STICKER CLASSIC	\$	100.00	151n
TOTAL	\$	505.00	

TOTAL PARTS \$ 14,364.65**LABOUR**

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	1201
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201
Putty and spray painting of the affected portion.	\$	1,400.00	11001
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	10001
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
TOTAL	\$	4,360.00	

Over All Total \$ 18,724.65**(LUMPSUM) Repair Days****20 Days**
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: