

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD777B**AAD2101-097***Not Authorized
C/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 JAN 2021**SHD777B**

VF1ABL15AUC283310

RENAULT

LATITUDE

20/01/2021

CHINA

31/08/2016

PART	LIST
1 DOOR PANEL FRT RH	\$ <i>B</i> 2,844.66 ✓
1 DOOR WEATHERSTRIP FRT RH	\$ <i>SVC</i> 410.27 7X
1 DOOR HANDLE OUTER FRT RH	\$ <i>h</i> 477.76 X
1 DOOR HANDLE MODULE FRT RH	\$ <i>h</i> 133.60 X
1 DOOR REGULATOR FRT RH	\$ <i>ori</i> 505.19 ✓
1 DOOR REGULATOR MOTOR FRT RH	\$ <i>h</i> 796.46 ✓
1 DOOR HINGE UPPER FRT RH	\$ <i>R</i> 261.28 X
1 DOOR HINGE LOWER FRT RH	\$ <i>h</i> 300.55 ^
1 CENTRE PILLAR OUTER	\$ <i>B</i> 880.14 ✓
1 CENTER PILLAR INNER	\$ <i>R</i> 907.76 7X
1 DOOR PANEL REAR RH	\$ <i>B</i> 2,844.66 ✓
1 DOOR WEATHERSTRIP REAR RH	\$ <i>ori</i> 311.60 50h
1 DOOR REGULATOR REAR RH	\$ <i>SVC</i> 450.60 7X
1 DOOR REGULATOR MOTOR REAR RH	\$ <i>SVC</i> 758.10 7X
1 DOOR HINGE UPPER REAR RH	\$ <i>SVC</i> 241.60 7X
1 DOOR HINGE LOWER REAR RH	\$ <i>B</i> 169.90 ✓
1 DOOR MIRROR ASSY RH	\$ <i>h</i> 1,483.40 X
1 FENDER PANEL FRT RH	\$ <i>R</i> 437.10 X
1 ROCKER PANEL OUTER RH	\$ <i>B</i> 1,184.99 ✓
TOTAL	\$ 15,399.61
10%	\$ 1,539.96
	\$ 13,859.65

Special Nett

1 DOOR TRIM CLIP	\$ <i>nn</i> 70.00 X
1 DOOR SEAL CLIP	\$ <i>nn</i> 65.00 X
1 DOOR MOULDING CLIP	\$ <i>nn</i> 70.00 X

Trans-cab Auto Services Pte Ltd**AAD2101-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G


SHD777B

1 DOOR STICKER TRANSCAB	\$	100.00	601n
1 DOOR STICKER 65553333	\$	100.00	601n
1 DOOR STICKER CLASSIC	\$	100.00	151n
TOTAL	\$	505.00	

TOTAL PARTS \$ 14,364.65**LABOUR**

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	1201
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201
Putty and spray painting of the affected portion.	\$	1,400.00	11001
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	10001
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

To check steering geometry and computer wheel alignment	\$	~ 220.00	X
TOTAL	\$	4,360.00	

Over All Total \$ 18,724.65**(LUMPSUM) Repair Days****20 Days**
7 days

Trans-cab Auto Services Pte Ltd**AAD2101-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD777B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD777B

VF1ABL15AUC283310

RENAULT

LATITUDE

20/01/2021

CHINA

31/08/2016

SUPPLEMENTARY**PART****LIST**

1 DOOR HARNESS WIRE FRT RH

\$ *Sm* 2,670.00 X1 ~~set~~ DOOR HARNESS WIRE REAR RH\$ *CMA* 2,670.00 ✓**TOTAL \$ 5,340.00****10% \$ 534.00****\$ 4,806.00**