

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7996A**AAD2101-061***Not Authorized**Return B4 part*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

22 JAN 2021

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB7996A

JTDKB3FU903080363

TOYOTA

PRIUS

10/01/2021

AIG

24/05/2019

- | | PART | LIST | |
|---|-------------------------------------|-------------|----------|
| 1 | COVER, REAR BUMPER | \$ | 442.60 ✓ |
| 1 | GUARD, REAR BUMPER, CENTER | \$ | 576.30 ✓ |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER | \$ | 332.70 ? |

TOTAL \$ 1,351.60

25% \$ 337.90

\$ 1,013.70**Special Nett**

1SET PARKING AID

1SET REAR BUMPER CLIP

\$	700.00	X
\$	95.00	600

TOTAL \$ 795.00**TOTAL PARTS \$ 1,808.70****LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$	380.00	X
----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	2,200.00	200
----	----------	-----

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	380.00	X
----	--------	---

To transfer of Tailgate fittings, attachments and perform water seepage test.

TOTAL \$ 180.00 X

Trans-cab Auto Services Pte Ltd**AAD2101-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7996A

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	11,268.70	
	\$	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	2200
To reinstall rear bumper parking sensor.	\$	170.00	500
To Check Electrical Lighting Concerned.	\$	170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To lift-up / out engine with gear box and refit.	\$	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	X
TOTAL	\$	9,460.00	