

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7996A****AAD2101-061***Not Notion**Referring B4 part**81294.18*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**22 JAN 2021****SHB7996A**

JTDKB3FU903080363

TOYOTA

PRIUS

10/01/2021

**AIG**

24/05/2019

**PART**

- 1 COVER, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER

**LIST**\$ *Bu* 442.60 ✓\$ *Notion* ~~576.30~~ ✓ *576.31*\$ *R* 332.70 ✗**TOTAL \$ 1,351.60****25% \$ 337.90****\$ 1,013.70****Special Nett**

1SET PARKING AID

1SET REAR BUMPER CLIP

\$ *Sn* 700.00 ✗\$ *me* 95.00 *6000***TOTAL \$ 795.00****TOTAL PARTS \$ 1,808.70****LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 ✗

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *2000*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *h* 380.00 ✗

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *h* 180.00 ✗

**Trans-cab Auto Services Pte Ltd****AAD2101-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7996A**

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	h	480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	h	380.00	X
To check steering geometry and computer wheel alignment	\$	h	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	2200
To reinstall rear bumper parking sensor.	\$		170.00	500
To Check Electrical Lighting Concerned.	\$	h	170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	h	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	h	220.00	X
To replace, refix and top up coolant for radiator	\$	h	170.00	X
To lift-up / out engine with gear box and refit.	\$	h	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	h	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	h	380.00	X
<b>TOTAL</b>	<b>\$</b>		<b>9,460.00</b>	

**Trans-cab Auto Services Pte Ltd**

**AAD2101-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7996A**

Over All Total	\$	<b>11,268.70</b>
----------------	----	------------------

**(PART-BY-PART) Repair Days**

**25 DAYS**

*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: