



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11731/ANGELINE SOO CHYIN LING Reg No/Reg Date SGF7549Z / 03/01/202 Date In/Mileage / 20909 Chassis No KNAF5416ML5059880 Engine No G4FGKH738881 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 17:01	BLE	261 / Edwin Caina	28021			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW BONNET , FRT BUMPER , LHF FENDER & LHF DOOR REPAIR LHF DOOR PILLAR , LH CENTRE PULLAR , LHF WHEELHOUSE & LHR DOOR					490 X 4			1609 2800.00
E PNT98000 RESPRAY FRT BUMPER , LHF FENDER , LHF WHEELHOUSE PNL , BONNET , LHF DOOR, PILLAR , LHF DOOR , LHR DOOR & LH SIDE SILL GARNISH					350 X 5			1750 3150.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR								100.00
M SUNDRY TOP UP AIRCON GAS								80.00
E PNT88000 REMOVE & REFIT LHF DOOR COMPONENT								120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING								50.00
E PNT88000 REMOVE & REFIT FRT PARKING ASSIST SESNOR								60.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
M SUNDRY SUPPLY BODY PNL SEALANT								80.00
M SUNDRY Sundries								20.00
M LAMP ASSY-HEAD, LH					1.00	2210.00	20.00	1768.00
M PANEL ASSY-HOOD					1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, LH					1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, RH					1.00	43.00	20.00	34.40
M CLIP-HOOD INSULATING PAD MTG					(9) 13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD					1.00	103.00	20.00	82.40

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11731/ANGELINE SOO CHYIN LING Reg No/Reg Date SGF7549Z / 03/01/202 Date In/Mileage / 20909 Chassis No KNAF5416ML5059880 Engine No G4FGKH738881 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/01/2021/ 17:01	BLE	261 / Edwin Caina	28021			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL-FENDER,LH	✓ 00 ? CR4			1.00	430.00	20.00	344.00
M	GUARD ASSY-FRONT WHEEL,LH	✓ ? X NN			1.00	95.00	20.00	76.00
M	CARRIER ASSY-FRONT END MODULE	✓ ? X NN			1.00	675.00	20.00	540.00
M	BEAM COMPLETE-FR BUMPER	✓ X NN			1.00	497.00	20.00	397.60
M	COVER-FR BUMPER	✓ 00			1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER	✓ 00			1.00	485.00	20.00	388.00
M	LAMP ASSY-FRONT FOG,LH	✓ ? X NN			1.00	303.00	20.00	242.40
M	MOULDING-FRONT BUMPER,LH	✓ ? X NN			1.00	216.00	20.00	172.80
M	LAMP ASSY-SIDE REPEATER,LH	✓ ? X NN			1.00	143.00	20.00	114.40
M	AIR DUCT-FR BUMPER,LH	✓ ? X NN			1.00	14.00	20.00	11.20
M	ABSORBER-FRONT BUMPER ENERGY	✓ X NN			1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR	✓ X NN			1.00	114.00	20.00	91.20
M	BRACKET-FR BUMPER UPR SIDE	✓ X NN			1.00	22.00	20.00	17.60
M	WIRING ASSY-BUMPER EXTENSION	✓ X NN			1.00	207.00	20.00	165.60
M	ULTRASONIC SENSOR ASSY-P.A.S	✓ X NN			2.00	163.00	20.00	260.80
M	ORNAMENT-KIA NO.115	✓ RC			1.00	32.00	20.00	25.60
M	GARNISH-RADIATOR GRILLE	✓ X NN			1.00	38.00	20.00	30.40
M	GRILLE ASSY-RADIATOR	✓ X NN			1.00	328.00	20.00	262.40
M	MOULDING ASSY-SIDE SILL,LH	✓ X NN			1.00	279.00	20.00	223.20
M	PANEL ASSY-FRONT DOOR,LH	✓ 00			1.00	1277.00	20.00	1021.60
M	HINGE ASSY-FRT DOOR UPP,LH	✓ ? = BT			1.00	30.00	20.00	24.00
M	HINGE ASSY-FRT DOOR LWR,LH	✓ ? = BT			1.00	27.00	20.00	21.60
M	BLACK TAPE-FR DR RR,LH	✓ RC			1.00	13.00	20.00	10.40
M	LATCH ASSY-FRONT DOOR,LH	✓ X NN			1.00	400.00	20.00	320.00
M	MOULDING ASSY-FRT DR FRAME,LH	✓ RC			1.00	72.00	20.00	57.60
M	W/STRIP ASSY-FR DR BELT O/S RH	✓ X NN			1.00	80.00	20.00	64.00
M	W/STRIP ASSY-FR DR SIDE LH	✓ X NN			1.00	102.00	20.00	81.60
M	W/STRIP-FR DR BODY SIDE LH	✓ X NN			1.00	125.00	20.00	100.00
M	W/STRIP-FR DR BELT I/S LH	✓ X NN			1.00	43.00	20.00	34.40
M	COOLANT (4L)	✓ ? X NN			1.00	26.00	23.00	20.02
SURVEYOR NAME: Steve CLKK 26/1/21, 10.30am					15,863.22			

Confirm & accepted by

SURVEYOR SIGNATURE: OB-NH A/L

DATE: EXP 15-?

REMARKS: P/P

Nett

15513.22

Total Payable

15,513.22

1085.93

16,599.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.