

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMC 2308E
 at Workshop m/s Koh mter Han
 of _____
 Insured: GS68458A
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMC 2308E Yr Regn: 28/6/18
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Honda HRV c.c. 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 34936 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMRU1830GX204006
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: _____

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: \$ 77k.
 IDAC Accident Rpt: _____ Consistent?: **Yes** or **No**
 GIA / PR Seen: _____ Consistent?: **Yes** or **No**
 Est. Repairs: 6 days Res.: **Yes** or **No**
 Lum Sum: 1.31 % 3 Val.: **Yes** or **No**
 CA / REV / REP. / 24 HRS 3312
 Date: _____ Person Contacted: _____
 Vehicle: **IN / OUT**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 Rear 6
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 2/1/21 D.O.I. 29/1/21
 Survey held at _____
 Des. of Damages: **Frnt / Rear / O/S / N/S / U/C / Rooftop** or
N/S R.R.
 The **U/C / Chassis frame / Body Structure** affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
| | <u>20286</u> |
| | <u>LYA # 43321</u> |

19/2/21 9/7 # 8489.54 confirmed with Ary

Date/Time, File Pass to? : **Preli. Report** Days Of Repair: _____
 : **Final Report** Resurvey No. of Trip: _____
 Date/Time, File Return to? _____ Survey Fee: _____
 1) _____ Transportation: _____
 2) _____ Add Fee: : Site Insp (\$) S + RS SI
 : Interview (\$) Photos
 : Tech. Invs (\$) Others
 : Weekend (\$)
 Report Format : _____
 Lump Sum / I.B.I: (\$) _____) TOTAL _____



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

Fax = 62962706

Customer : LONPAC INSURANCE BHD
 300 BEACH ROAD #17-04/07
 THE CONCOURSE
 SINGAPORE 199555

Registration No : SMC2308E
Chassis No : JHMRU1830GX204006
Model : HRV LX-SIN CVT YM 2016
Owner's Name : KOH SEO LENG
Ins Policy No. : SD20V06156/VPC2/R01
Date of Accident : 22/1/2021

Document No. : SQT21000282 **Page** 1
Date : 22. Jan 2021
Customer No. : WZL009
Svc Advisor : ARY CHUA WAI NGREE
Engine No : L15B4534010
Date | Time : 22. Jan 2021 4:15:12 PM
Surveyor Name : CID : +65 6346 5673
Survey Date : HP : +65 8100 6306
Authorisation Date : Email : anychua@honda.com.sg

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|---|-----|------------|--------|---------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO: 75667) OWNER: KOH SEO LENG OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 22/01/2021@12.30PM SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC INSURANCE BHD TP VEH: GBG8458A - SUZUKI/EVERY/GRAY | | | | | | |
| 33150-T7S-E11 | HEAD LIGHT ASSY,L. <i>one</i> | 1 | 1869.00 | ✓ 25 | 1401.75 | 98.12 | 1499.87 |
| 33950-SLE-J51 | LIGHT ASSYL.FR.FOGLIGHT <i>one</i> | 1 | 245.90 | ✓ 25 | 184.42 | 12.91 | 197.33 |
| 71106-T7A-000 | GARNISHL.FR.FOG LIGHT <i>one</i> | 1 | 22.10 | X 25 | 16.57 | 1.16 | 17.73 |
| 91505-TM8-003 | CLIP,BUMPER <i>one</i> | 14 | 2.30 | ✓ 25 | 24.15 | 1.69 | 25.84 |
| 19043-PNB-A00 | LABELCOOLANT INFORMATION <i>one</i> | 1 | 5.20 | ✓ 25 | 3.90 | 0.27 | 4.17 |
| 04711-T7A-N00ZZ | FACE,FR.BUMPER <i>one</i> | 1 | 487.90 | ✓ 25 | 365.92 | 25.61 | 391.53 |
| 71130-T7A-010ZZ | BEAM COMP,FR.BUMPER <i>one</i> | 1 | 228.80 | ✓ 25 | 171.60 | 12.01 | 183.61 |
| 71110-T7A-000 | SPOILERFR.BUMPER AIR <i>one</i> | 1 | 56.30 | X 25 | 42.22 | 2.96 | 45.18 |
| 04712-T7A-900ZZ | FACEFR.BUMPER LOWER <i>one</i> | 1 | 237.60 | X 25 | 178.20 | 12.47 | 190.67 |
| 71190-T7A-000 | BEAML.FR.BUMPER UPPER <i>one</i> | 1 | 26.90 | ✓ 25 | 20.17 | 1.41 | 21.58 |
| 71198-T7A-J00 | SPACER,L.FR.BUMPER SIDE <i>one</i> | 1 | 11.30 | ✓ 25 | 8.47 | 0.59 | 9.06 |
| 74165-T7A-000 | GUARD SETL.FR.SPLASH <i>one</i> | 1 | 45.00 | ✓ 25 | 33.75 | 2.36 | 36.11 |
| 74150-T7A-N00 | FENDER ASSYL.FR.INNER <i>one</i> | 1 | 92.30 | ✓ 25 | 69.22 | 4.85 | 74.07 |
| 74157-T7A-J012C | PROTECTOR,L.FR.WHEEL ARCH <i>one</i> | 1 | 157.60 | ✓ 25 | 118.20 | 8.27 | 126.47 |
| 60260-T7A-J00ZZ | PANEL COMPL.FR.FENDER <i>one</i> | 1 | 405.20 | ✓ 25 | 303.90 | 21.27 | 325.17 |
| 74155-T7A-000 | ENCLOSUREL.FR.FENDER <i>one</i> | 1 | 10.90 | X 25 | 8.17 | 0.57 | 8.74 |
| 74141-T7A-000 | INSULATORHOOD <i>one</i> | 1 | 112.60 | ✓ 25 | 84.45 | 5.91 | 90.36 |
| 60120-T7A-000ZZ | HINGE COMPR.HOOD <i>one</i> | 1 | 40.90 | ✓ 25 | 30.67 | 2.15 | 32.82 |
| 60170-T7A-000ZZ | HINGE COMPL.HOOD <i>one</i> | 1 | 40.90 | ✓ 25 | 30.67 | 2.15 | 32.82 |

LKK Auto Consultants hence notify the Repairer

- To resurvey vehicle after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 22/1/2021 6:14:20 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMC2308E
Chassis No : JHMRU1830GX204006
Model : HRV LX-SIN CVT YM 2016
Owner's Name : KOH SEO LENG
Ins Policy No. : SD20V06156/VPC2/R01
Date of Accident : 22/1/2021

Document No. : SQT21000282 **Page** 2
Date : 22. Jan 2021
Customer No. : WZL009
Svc Advisor : ARY CHUA WAI NGENE
Engine No : L15B4534010
Date | Time : 22. Jan 2021 4:15:12 PM
Surveyor Name :
Survey Date :
Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|------------------|---|-----|------------|--------|----------------|---------------|------------------|
| 60400-T7A-901ZZ | BULKHEAD COMP.FR. <i>R</i> | 1 | 445.70 | X 25 | 334.27 | 23.40 | 357.67 |
| 60710-T7A-300ZZ | MEMBER COMPL.FR.WHEELHOUSE UP <i>an</i> | 1 | 96.10 | X 25 | 72.07 | 5.04 | 77.11 |
| 04684-T7A-300ZZ | EXTENSION SETL.FR.SHOCK ABS <i>Bed 500</i> | 1 | 96.80 | X 25 | 72.60 | 5.08 | 77.68 |
| 60630-T7A-000ZZ | BASE COMPBATTERY SETTING <i>an</i> | 1 | 70.50 | X 25 | 52.87 | 3.70 | 56.57 |
| 60100-T7A-000ZZ | HOOD COMP ENGINE <i>Buc</i> | 1 | 821.70 | X 25 | 616.27 | 43.14 | 659.41 |
| Sum Item | | | | | 4244.48 | 297.09 | 4,541.57 |
| BOSUN | SUNDRIES <i>nel</i> | 1 | 50.00 | 20 | 50.00 | 3.50 | 53.50 |
| BOBC | BODY UNDERSIDE COATING (N) <i>an</i> | 1 | 100.00 | X | 100.00 | 7.00 | 107.00 |
| BOJSE | BODY JOINT SEALANT. <i>nel</i> | 1 | 100.00 | X | 100.00 | 7.00 | 107.00 |
| BML01I | INSPECT FR LIGHTING MECHANISMS & FOCUS | 1 | 180.00 | 120 | 180.00 | 12.60 | 192.60 |
| BP00R | APPLY BODY UNDERSIDE COATING (N). <i>an</i> | 1 | 250.00 | X | 250.00 | 17.50 | 267.50 |
| BMC01D | REMOVE & INSTALL RADIATOR WITH FITTINGS. <i>an</i> | 1 | 350.00 | X | 350.00 | 24.50 | 374.50 |
| BMA01D | REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. <i>an</i> | 1 | 450.00 | X | 450.00 | 31.50 | 481.50 |
| BKBH11B | RENEW BULKHEAD, WHEELHOUSE EXTENSION & ALIGN CHASS <i>650</i> | 1 | 2800.00 | 1950 | 2800.00 | 196.00 | 2996.00 |
| BP05R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) <i>500</i> | 1 | 3200.00 | 2600 | 3200.00 | 224.00 | 3424.00 |
| Sum Labor | | | | | 7480.00 | 523.60 | 8,003.60 |

Survey By: marcus lth
 Date & Time: 29/1/21 @ 11:30am
 Excess: _____
 Status: not Authorised
 Signature: The Sh. Sekizawa

Total Amount 11,724.48 820.69 12,545.17
Total (Inclusive of GST) 12,545.17

6 days.
 Supplementary 1. Front Grille outer crack *one*
 2. LHF Fog L/H: 33966 - T7A-J00 *one*

Printed on 22/1/2021 6:14:20 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0051446 / KOH SEO LENG
Chassis No: JHMRU1830GX204006
License No: SMC2308E
Mileage: 34935
Engine No: L15B4534010

Document No: SVO21005923
Printed By: ARYCHUA
Order Date: 29. January 2021
Order Time: 12:05:42 PM
Service Advisor: ARY CHUA WAI NGENE

| ITEM | DESCRIPTION | QTY | UNIT PRICE | DISC % | AMOUNT | 7% GST Amount | Incl GST |
|---|-------------------------|-----|------------|--------|---------------|---------------|---------------|
| SUPPLIMENTARY ITEM PARTS & LABOR | | | | | | | |
| 33966-T7A-J00 | BRACKETL.FOG LIGHT | 1 | 51.30 | 25 | 38.47 | 2.69 | 41.16 |
| 71122-T7A-901 | MOLDINGFR.GRILLE UPPER | 1 | 194.70 | 25 | 146.02 | 10.22 | 156.24 |
| 60723-T7A-300ZZ | BRACKETL.FR.FENDER | 1 | 13.50 | 25 | 10.12 | 0.71 | 10.83 |
| 33950-SLE-J51 | LIGHT ASSYL.FR.FOGLIGHT | 1 | 245.90 | 25 | 184.42 | 12.91 | 197.33 |
| SUM PARTS: | | | | | 379.03 | 26.53 | 405.56 |
| TOTAL SGD | | | | | 379.03 | 26.53 | 405.56 |

Total Payable (SGD)

405.56

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0051446 / LONPAC
Chassis No: JHMRU1830GX204006
License No: SMC2308E
Mileage: 34935
Engine No: L15B4534010

Document No: SVO21005923
Printed By: ARYCHUA
Order Date: 29. January 2021
Order Time: 12:05:42 PM
Service Advisor: ARY CHUA WAI NGEE

| ITEM | DESCRIPTION | QTY | UNIT | DISC % | AMOUNT | 7% GST Amount | Amount Incd GST |
|-----------------|--|-----|----------|--------|-----------------|---------------|-----------------|
| | TP DIRECT SETTLEMENT (J/NO: 75667) OWNER: KOH SEO LENG OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 22/01/2021@12.30PM ACC: NEAR 827 BKT TIMAH RD S279886 SURVEYED BY: MARCUS CHUA (LKK)29/01/2021@12.12PM REF NO: CC4/LPC21001201/BA3 TP INSURER: LONPAC INSURANCE BHD TP VEH: GBG8458A - SUZUKI/EVERY/GRAY | | | | | | |
| 33150-T7S-E11 | HEAD LIGHT ASSY,L. | 1 | 1,869.00 | 25 | 1,401.75 | 98.12 | 1,499.87 |
| 91505-TM8-003 | CLIP,BUMPER | 14 | 2.30 | 25 | 24.15 | 1.69 | 25.84 |
| 19043-PNB-A00 | LABELCOOLANT INFORMATION | 1 | 5.20 | 25 | 3.90 | 0.27 | 4.17 |
| 04711-T7A-N00ZZ | FACE,FR.BUMPER | 1 | 487.90 | 25 | 365.92 | 25.61 | 391.53 |
| 71130-T7A-010ZZ | BEAM COMP,FR.BUMPER | 1 | 228.80 | 25 | 171.60 | 12.01 | 183.61 |
| 71190-T7A-000 | BEAML.FR.BUMPER UPPER | 1 | 26.90 | 25 | 20.17 | 1.41 | 21.58 |
| 71198-T7A-J00 | SPACER,L.FR.BUMPER SIDE | 1 | 11.30 | 25 | 8.47 | 0.59 | 9.06 |
| 74165-T7A-000 | GUARD SETL.FR.SPLASH | 1 | 45.00 | 25 | 33.75 | 2.36 | 36.11 |
| 74150-T7A-N00 | FENDER ASSYL.FR INNER | 1 | 92.30 | 25 | 69.22 | 4.85 | 74.07 |
| 74157-T7A-J01ZC | PROTECTOR,L.FR.WHEEL ARCH | 1 | 157.60 | 25 | 118.20 | 8.27 | 126.47 |
| 60260-T8N-T20ZZ | PANEL COMP,L.FR.FENDER | 1 | 358.30 | 25 | 268.72 | 18.81 | 287.53 |
| 74141-T7A-000 | INSULATORHOOD | 1 | 112.60 | 25 | 84.45 | 5.91 | 90.36 |
| 60120-T7A-000ZZ | HINGE COMPR.HOOD | 1 | 40.90 | 25 | 30.67 | 2.15 | 32.82 |
| 60170-T7A-000ZZ | HINGE COMPL.HOOD | 1 | 40.90 | 25 | 30.67 | 2.15 | 32.82 |
| 04684-T7A-300ZZ | EXTENSION SETL.FR.SHOCK ABS | 1 | 96.80 | 25 | 72.60 | 5.08 | 77.68 |
| 60100-T7A-000ZZ | HOOD COMP ENGINE | 1 | 821.70 | 25 | 616.27 | 43.14 | 659.41 |
| 33966-T7A-J00 | BRACKETL.FOG LIGHT | 1 | 51.30 | 25 | 38.47 | 2.69 | 41.16 |
| 71122-T7A-901 | MOLDINGFR.GRILLE UPPER | 1 | 194.70 | 25 | 146.02 | 10.22 | 156.24 |
| 60723-T7A-300ZZ | BRACKETL.FR.FENDER | 1 | 13.50 | 25 | 10.12 | 0.71 | 10.83 |
| 33950-SLE-J51 | LIGHT ASSYL.FR.FOGLIGHT | 1 | 245.90 | 25 | 184.42 | 12.91 | 197.33 |
| | SUM PARTS: | | | | 3,699.54 | 258.95 | 3,958.49 |
| BOSUN | 0760 SUNDRIES | 1 | 20.00 | | 20.00 | 1.40 | 21.40 |
| BOJSE | 0760 BODY JOINT SEALANT. | 1 | 100.00 | | 100.00 | 7.00 | 107.00 |
| BML01I | EXT-YJ INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N) | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BKBH11B | EXT-YJ RENEW BULKHEAD, WHEELHOUSE EXTENSION & ALIGN CHASS INCLUDING FITTING ON ATTACHMENT ITEMS | 1 | 1,950.00 | | 1,950.00 | 136.50 | 2,086.50 |
| BP05R | EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P) | 1 | 2,600.00 | | 2,600.00 | 182.00 | 2,782.00 |
| | SUM LABOUR: | | | | 4,790.00 | 335.30 | 5,125.30 |
| | TOTAL SGD | | | | 8,489.54 | 594.25 | 9,083.79 |

WD = 6

Total Payable (SGD)

9,083.79