

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

CN - ER
Adrian
LKL

21/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPEQ
Xiao Chan.

Accident date: 21/01/2021

Estimated repair cost for vehicle no: SCF9896E SUBARU FORESTER 2.0 CVT '16

CHASSIS: JF1SJGK85GG076472

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$1,192.30
2	2	Rear Boot Lid Hinge	\$55.00	\$110.00
3	2	Rear Boot Lid Shock Absorber	\$154.00	\$308.00
4	1	Rear Boot Lid Emblem Logo		\$65.00
5	1	Rear Boot Lid Subaru Logo		\$68.00
6	1	Rear Boot Lid Forester Logo		\$68.00
7	1	Rear Boot Lid AWD Logo		\$65.00
8	1	Rear Boot Lid Number Plate		\$50.00
9	1	Rear Boot Lid Inner Lock		\$560.30
10	1	Rear Boot Lid Weatherstrip		\$160.30
11	1	Rear Boot Lid Inner Trim Board		\$220.30
12	10	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$65.00
13	1	Rear Boot Lid Windscreen Seal		\$85.00
14	2	Rear Boot Lid Windscreen Side Seal	\$75.00	\$150.00
15	1	Rear Boot Lid Reverse Camera		\$850.00
16	2	Rear Tail Lamp	\$437.30	\$874.60
17	4	Rear Tail Lamp Clip	\$8.00	\$32.00
18	2	Rear Tail Lamp Panel	\$105.80	\$211.60
19	2	Rear Tail Lamp Lower Bracket	\$28.00	\$56.00
20	1	Rear Bumper		\$980.30
21	10	Rear Bumper Clip	\$6.50	\$65.00
22	1	Rear Bumper Top FORESTER Moulding		\$620.00
23	2	Rear Bumper Side Retainer	\$38.00	\$76.00
24	2	Rear Bumper Side Reflector	\$42.00	\$84.00
25	1	Rear Bumper Towing Cover		\$22.00
26	1	Rear Bumper Reinforcement		\$320.80
27	2	Rear Bumper Reinforcement Bracket	\$28.60	\$57.20
28	1set	Rear Bumper Lower Reinforcement		\$1,250.00
29	2	Rear Bumper Lower Reinforcement Bracket	\$220.00	\$440.00
30	1	Rear Bumper Reverse Sensor (Special Nett)		\$380.00

31	2	Rear Fender <i>Rego</i>	\$1,060.40	\$2,120.80 X
32	2	Rear Fender Inner Trim Board <i>Debond</i>	\$286.30	\$572.60 ✓
33	16	Rear Fender Inner Trim Board Clip <i>re</i>	\$6.50	\$104.00 ✓ 60
34	1	Rear End Panel <i>Dented</i>		\$589 ✓
35	1	Rear End Panel Top Garnish <i>Debond</i>		\$90.00 ✓
36	1	Rear Spare Tyre Panel <i>Buckle</i>		\$32.40 ✓
37	1	Rear Spare Tyre Panel Top Cover <i>Debond</i>		\$832.40 ✓
38	1	Rear Spare Tyre Panel & End Panel Sealant <i>xtor</i>		\$336.00 ✓
39	1	Rear Spare Tyre Panel Foam Tool Box <i>crushed</i>		\$450.00 X
40	1	Rear Spare Tyre Panel Under Foam <i>crushed</i>		\$161.20 ✓
41	2	Rear Exhaust <i>Bent LH</i>	\$785	\$60.00 ✓ 785
42	1	Rear Centre Exhaust <i>Bent</i>		\$1,048.40 ✓
43	1	Rear Exhaust Aluminium Cover <i>3 MP</i>		\$86.00 X
44	2	Rear Exhaust Mounting <i>for</i>	\$23.10	\$46.20 X

Subtotal :- \$16,876.30

Labour charges

To remove & refit cushion & trim board

~~\$280.00~~ 180

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit reverse camera

~~\$180.00~~ X

To remove & refit rear & centre exhaust

~~\$380.00~~ 200

To remove & refit rear windscreen

2780 ~~\$150.00~~ X

Gum

~~\$60.00~~ X

To check wiring

2600 ~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 120

Panel beating

~~\$2,400.00~~ 200

Spray painting

~~\$2,000.00~~ 1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$5,800.00

Total:- \$22,676.30

7.61c

total: 9544.56
h/s: 7.61c
08 Days