



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.		Cust No/Name	/NIRMALA D/O SIVAGURU AYA DURAI
MOTOR CLAIM DEPT		Reg No/Reg Date	SMS3199L / 21/02/202
78 SHENTON WAY #09-16		Date In/Mileage	/ 0
AIG BUILDING		Chassis No	MMBSTA13AKH004956
SINGAPORE 079120		Engine No	3A92UJL6340
Contact No 6419 1892		Make/Model	MIT/19MY ATTRAGE 1.2 CVT
		Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	26/01/2021/ 10:52	QUD	247 / DonBong	62304		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2250.00
							2025
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT DOOR							
E PNT88000							100.00
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK							
A 55900099							80.00
TOP UP AIR CON GAS AND CHECK A/CON GAS							
E PNT88000							80.00
REMOVE AND REPLACE FRONT BODY KITS							
E PNT98000							3150.00
PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER FACE, FRONT BODY KITS RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR, LH FRONT DOOR AND Affected PORTION							2800
M SUNDAY							40
SUPPLY BODY SEALANT							120.00
A 54900099							30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDAY							40
PERFORM RUST PREVENTION							120.00
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDAY							50.00
SUPPLY FRONT NUMBER PLATE WITH FRAME							
M SUNDAY							20
SUNDRIES							50.00
M PANEL ASSY, FR END ✓ DD				1.00	1055.00	23.00	812.35
M PANEL, HEADLAMP SUPPORT, UPR ✓ DR				1.00	65.00	23.00	50.05
M MOTOR, COOLING FAN ? X NM				1.00	479.00	23.00	368.83
M SHROUD, COOLING FAN ? ✓ BL				1.00	130.00	23.00	100.10

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreens in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreens.



**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056**



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

**Invoice Name & Address**

AIG Asia Pacific Insurance Pte.  
Ltd.  
MOTOR CLAIM DEPT  
78 SHENTON WAY #09-16  
AIG BUILDING  
SINGAPORE 079120  
Contact No 6419 1892

<b>Cust No/Name</b>	/NIRMALA D/O SIVAGURU AYA DURAI
<b>Reg No/Reg Date</b>	SMS3199L / 21/02/202
<b>Date In/Mileage</b>	/ 0
<b>Chassis No</b>	MMBSTA13AKH004956
<b>Engine No</b>	3A92UJL6340
<b>Make/Model</b>	MIT/19MY ATTRAGE 1.2 CVT
<b>Colour/Trim</b>	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	26/01/2021/ 10:52	QUD	247 / DonBong	62304
<b>Description of Goods / Services</b>					
M FAN, COOLING,LH	X	AM		Qty	Unit Price
M RADIATOR ASSY	?	OR			Disc%
M PANEL,AIR GUIDE	?	BR			Amount
M CONDENSER ASSY,A/C REFRIGE	?	OT			
M PANEL,AIR GUIDE,RH	?	OR			
M PANEL,AIR GUIDE,LH	?	BR			
M LLC 4L	?	X AM			
M HEADLAMP ASSY,LH	?	BR			
M HEADLAMP ASSY,RH	?	BR			
M MARK, THREE-DIA	?	NC			
M GRILLE,RADIATOR	?	BR			
M BRACKET,FR BUMPER,LH	?	BR			
M BRACKET,FR BUMPER,RH	?	BR			
M GRILLE,FR UNDER	?	BR			
M GARNISH,FR BUMPER,LH	X	NM			
M GARNISH,FR BUMPER,RH	X	NM			
M COVER,HEADLAMP SUPT PANEL	?	BR			
M CLIP,FR BUMPER	?	NC			
M FACE,FR BUMPER	?	BR			
M COVER,FR BUMPER	(TL eye cov.)	~ MIS			
M HOOD	?	00			
M HINGE,HOOD,LH	?	BT			
M HINGE,HOOD,RH	?	BT			
M INSULATOR,HOOD	X	NM			
M CLIP,HOOD INSULATOR	?	NC X NN			
M LATCH,HOOD	X	NM			
M FENDER,FR LH	?	00			
M FENDER,FR RH	?	00			
M EMBLEM ECO	?	NC			
M BODY KIT ATTRAGE	?	BR			
M HORN	?	X NM			
(SGW 5899 Salvage) / BR					
SURVEYOR NAME: <u>Steve CLKK</u>					
SURVEYOR SIGNATURE: <u>00-Ah1 AL</u>					
EXCESS - ?					

**Confirm & accepted by**

DATE:

REMARKS: 26/1/21, 2.90 pm

Nett

14,788.51

1035.20

7% GST on

14788.51

Total Payable

15,823.71

KK Auto Consultants hence notify  
the Repairer of the following:  
To resurvey before/after spray painting  
To display damaged part(s) during resurvey  
Parts prices are subject to confirmation  
Third party

**Authorized Signatory and company stamp**

No illegal substances are to be present at the repair shop.  
Supplier's estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include  
any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered  
after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a  
deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or  
cheque. You must also agree to pay full amount for renewal of the windscreens in the event of inadvertent breakage in the course of renewing  
the rubber seal or other repair requiring the removal of the windscreens.