Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

LKK Auto Consultants Pte Ltd From: 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

22 Feb 2021

Attn: Adeline Chng Pei Wen

Preliminary Advice

Date:

Insured Vehicle No : SLB3988C

TP Vehicle No : SML4487K Accident Date : 23/01/2021 Make : MAZDA 3 Assignment Date : 26/01/2021

Date of Inspection : 26/01/2021 Est. Duration of Repair : 2

Inspection At : C.S. ONG AUTO PTE LTD (AMK)

10 ANG MO KIO INDUSTRIAL PARK 2A, #02-16, AMK AUTO POINT

SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,725.44
Revised Amount	:S\$	1,289.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,289.68
Lump Sum Repair	:S\$	1,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments :