



Section A - Accident Details

Registration Number	SHB1196G
Case Reference Number	TAX/01/21/2050
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LAU OW PHENG
Type of Accident	Side Swipe
Accident Date and Time	25/1/2021 10:40 AM
Accident Reported Date and Time	25/1/2021 12:54 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109561
Special Instruction to ARC, if any	TP / LEFT PORTION / NTUC - LKK
Prepared Date and Time	26/1/2021 1:30 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,095.00	\$600.00
Total Spray Cost	\$2,592.00	\$880.00
Total Spare Part Cost	\$12,220.59	\$1,918.59
Total Other Cost	\$970.00	(\$498.59)
TOTAL COST	\$16,877.59	\$2,900.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	29/01/2021 3:30 PM	28/01/2021 11:01 AM
Signature	 	
Remarks	Total number of repair days = 4 days. SUP = +1 day.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2102-0164	Invoice Number	
Quotation Date	15.02.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PILLAR	\$250.00	\$100.00 /supp
TO REPAIR LH PORTION	\$845.00	\$500.00 /
Total Labour	\$1,095.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT PILLAR LH	\$180.00	\$100.00 /supp
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 /
RESPRAY MIRROR COVER LH	\$180.00	\$80.00 /
TO RESPRAY RIM	\$360.00	\$0.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 /
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 /
TO REPSRAY REAR DOOR LH	\$378.00	\$200.00 /
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,592.00	\$880.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00 / NRC	\$125.00 /supp
Lump Sum Adjustment by Surveyor	\$0.00	(\$743.59)
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$30.00 /
TO TRANSFER DOOR MECHANISM	\$240.00	\$60.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00 /
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
Total Other Costs	\$970.00	(\$498.59)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5380247100	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		5387647110	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given
		5385247041	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given

XR
/NRC
XSUC
XSUC
XSUC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 15/02/2021

User ID PohSuan

			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given
		6101447010	PILLAR, FRONT BODY, LH	0.00	\$339.40	0.00	\$0.00	Replace	Not Given
		7586047900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$576.00	100.00	\$0.00	Replace	Repair
		8794047440	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given
		8794547060A1	COVER, OUTER MIRROR, LH	1.00	\$89.50	100.00	\$0.00	Replace	Repair
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	25.00	\$937.20	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6872012151	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$82.10	0.00	\$0.00	Replace	Not Given
		6874012120	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given
		6980221010	DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	0.00	\$230.80	0.00	\$0.00	Replace	Not Given
		8572047140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Not Given
		6861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given
		6810247230	GLASS SUB-ASSY, FRONT DOOR, LH	0.00	\$796.70	0.00	\$0.00	Replace	Not Given
		6921047051A1	DOOR OUTER HANDLE FRONT, LH	1.00	\$378.90	25.00	\$284.18	Replace	Replace
		8215247551	WIRE, FRONT DOOR, LH	0.00	\$445.70	0.00	\$0.00	Replace	Not Given
		6700447210	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair
		6876020122	HINGE ASSY, REAR DOOR, UPPER LH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		6878052031	HINGE ASSY, REAR DOOR, LOWER LH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given
		7576447010	MOULDING, REAR DOOR WINDOW FRAME, UPPER LH	0.00	\$88.60	0.00	\$0.00	Replace	Not Given
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given
		6789647010	WEATHERSTRIP, REAR DOOR, NO.2, LH	0.00	\$33.20	0.00	\$0.00	Replace	Not Given
		4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given
		6563847060	LINER, REAR FENDER, LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given
Total					\$14,893.28		\$1,321.06		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		6810247230	GLASS SUB-ASSY, FRONT DOOR, LH	1.00	\$796.70	25.00	\$597.53	Replace	Replace
Total					796.70		597.53		

1918.59 /
+ 600.00 /
+ 1125.00 /

3643.59 /
- 202 /

2914.87 /

45 \$ 2900 /
4 days