

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0082/2021/GW
DATE	:	26/01/2021
WIP	:	63778

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS CHUNG LYE PENG
ADDRESS	:	20 TOH TUK CRESCENT SINGAPORE 596934
TELEPHONE	:	HP +65 97860896
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1700016379-03
VEHICLE NO	:	SLP 6864 H
MODEL CODE	:	AUDI Q2 1.0 TFSI
MODEL YEAR	:	14/06/2017
ENGINE NO	:	CHZ345025
CHASSIS NO	:	WAUZZZGA3HA040768
MILEAGE	:	
DATE IN	:	
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	25/01/2021
PLACE OF ACCIDENT	:	55 UBI ROAD 1, SINGAPORE 408699



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 6864 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	X
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNI AND POWER MODULE.	S/N \$ 400.00	250
4	TO RENEW AIRCON CONDENSER REFRIGERANT PIPE.	S/N \$ 280.00	X
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR COVER.	S/N \$ 280.00	✓
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1000
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR.	\$ 3,300.00	1650
8	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
SUB TOTAL LABOUR CHARGES		: \$ 11,484.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 6864 H

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>behind</i>	\$	1,758.00	✓
2 FRONT BUMPER CONNECTING PIECE-CENTER <i>new</i>	\$	148.00	+
3 FRONT BUMPER FIXING PARTS <i>new</i>	\$	347.00	+
4 FRONT BUMPER GRILLE-CENTER	\$	197.00	+
5 FRONT BUMPER AIR GUIDE GRILLE-LH <i>cut</i>	\$	169.00	✓
6 FRONT BUMPER END CAP-LH <i>new</i>	\$	59.00	+
7 FRONT BUMPER SPOILER <i>cut</i>	\$	299.00	✓
8 FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$	156.00	+
9 FRONT WHEEL SPOILER-LH <i>?</i>	\$	34.00	?
10 FRONT ADAPTER-LH <i>?</i>	\$	36.00	?
11 RADIATOR GRILLE <i>new</i>	\$	1,411.00	+
12 RADIATOR GRILLE STRICKER PLATE <i>new</i>	\$	124.00	+
13 FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	\$	723.00	+
14 FRONT FOAM FILLER PIECE	\$	78.00	+
15 FRONT BUMPER GUIDE SECTION-LH <i>?</i>	\$	36.00	?
16 FRONT BUMPER COVER <i>new</i>	\$	100.00	+
17 SIGN CAUTION STICKER <i>new</i>	\$	14.00	+
18 AIR CONDITIONER STICKER	\$	8.00	+
19 HORN -LH <i>new</i>	\$	286.00	+
20 SPRING SHACKLE -LH <i>new</i>	\$	31.00	+
SUB TOTAL SPARE PARTS	:	\$ 6,014.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 6864 H

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT FENDER-LH <i>Dented</i>		\$ 1,147.00	✓
22 FRONT FENDER ATTACHMENT PARTS <i>new</i>		\$ 40.00	+
23 FRONT FENDER BRACKET-LH ?		\$ 48.00	?
24 FRONT FENDER LEDGE COVER-LH INNER ?		\$ 16.00	?
25 FRONT FENDER LIEGE COVER-LH OUTER ?		\$ 16.00	?
26 FRONT FENDER BRACELH ?		\$ 44.00	?
27 FRONT WHEEL HOUSING LINER-LH ?		\$ 196.00	?
28 FRONT WHEEL HOUSING ATTACHMENT PARTS <i>new</i>		\$ 57.00	+
29 FRONT HEADLIGHT MOUNTING ?		\$ 118.00	?
30 LED HEADLIGHT-LH <i>cracked</i>		\$ 4,915.00	✓
31 LED HEADLIGHT POWER MODULE-LH ?		\$ 758.00	+
32 LED WITH HEAT SINK-LH <i>new</i>		\$ 733.00	+
33 LED HEADLIGHT CONTROL UNIT-LH		\$ 557.00	+
34 HOSE FOR HEADLIGHT WASHER SYSTEM <i>new</i>		\$ 30.00	+
35 LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM <i>new</i>		\$ 142.00	+
36 CONNECTOR HOSE FOR HEADLIGHT WASHER SYSTEM <i>new</i>		\$ 182.00	+
37 WASHER WATER RESERVOIR <i>new</i>		\$ 176.00	+
38 FRONT LOCK CARRIER <i>new</i>		\$ 994.00	+
39 RADIATOR COOLANT <i>new</i>	4	\$ 95.00	+
40 FRONT AIR GUIDE-LH <i>new</i>		\$ 31.00	+
SUB TOTAL SPARE PARTS	:	\$ 10,295.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 6864 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	REFRIGERANT LINER (A/C CONDENSER >CUT OFF POINT) <i>new</i>		\$	619.00	+
42	A/C SEAL RING <i>new</i>	2	\$	14.00	+
43	FRONT WHEEL COVER-LH/RH <i>LH cut, RH new</i>	2	\$	644.00	✓
44	FRONT ALUMINIUM RIM-LH <i>new</i>		\$	949.00	+
45	FRONT NO. PLATE <i>new</i>	S/N	\$	60.00	+
46	SUNDRIES ?		\$	300.00	?
TOTAL SPARE PARTS		:	\$	18,276.00	
TOTAL LABOUR CHARGES		:	\$	11,484.00	
GRAND TOTAL		:	\$	29,760.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *26/01/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT