

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 6864 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X ✓
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	X
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNI AND POWER MODULE.	S/N \$ 400.00	250 ✓
4	TO RENEW AIRCON CONDENSER REFRIGERANT PIPE.	S/N \$ 280.00	X
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR COVER.	S/N \$ 280.00	✓ ✓
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1000 ✓
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR.	\$ 3,300.00	1650 ✓
8	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓ ✓
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓ ✓
SUB TOTAL LABOUR CHARGES		: \$ 11,484.00	