



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Ref: CC4/ASM21001227/T1ba3q2 Date: 05/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3102D	Veh. Inspected	SLV 5938D
Policy No.	P2419138	Coverage (\$)	0.00
Claim No.	S1M0362Q	Excess (\$)	0.00
Assign From		Assign Date	26/01/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GK81200018	Colour	WHITE
Odometer	190408 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	TOURADOR	6 mm
L/H Front Tyre	185/60 R15	TOURADOR	6 mm
R/H Rear Tyre	185/60 R15	TOURADOR	6 mm
L/H Rear Tyre	185/60 R15	TOURADOR	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	15/01/2021	Inspection Date	28/01/2021
Survey held at	BLACK EAGLE AUTO PTE. LTD. 25 KAKI BUKIT ROAD 4 #05-80 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days