



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104556

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 29/06/2021  
Reference CC3/CTI21001230/T1es3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SMH 8243S  
Insured Veh. SLF 8826H  
Claim No. SNM21D200464/C02  
Policy No. DMPCSNA00121112004  
Accident Date 23/01/2021  
Inspection Date 26/01/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC3/CTI21001230/T1es3q2	
			Date: 29/06/2021	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLF 8826H	Veh. Inspected	SMH 8243S	
Policy No.	DMPCSNA00121112004	Coverage (\$)	0.00	
Claim No.	SNM21D200464/C02	Excess (\$)	0.00	
Assign From		Assign Date	26/01/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JM6BN22A8K0249290	Colour	GREY	
Odometer	24481 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	MAXXIS	6 mm	
L/H Front Tyre	205/60 R16	MAXXIS	6 mm	
R/H Rear Tyre	205/60 R16	MAXXIS	6 mm	
L/H Rear Tyre	205/60 R16	MAXXIS	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/01/2021	Inspection Date	26/01/2021	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 8243S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR O/S FENDER	BUCKLED	1,233.00	1,233.00
1	REAR WINDSCREEN MOULDING	NECESSARY	98.00	98.00
	LESS 20% DISCOUNT		-266.20	-266.20
			1,064.80	1,064.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SEALANT (SN)	NECESSARY	45.00	30.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			123.00	30.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE AND REFIT THE REAR WINDSCREEN .		120.00	120.00
	TO CHECK REAR O/S WHEEL ALIGNMENT .	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO CUT/WELD AND HEAT ON THE REAR O/S FENDER .INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR BUMPER ETC.		1,200.00	600.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,REAR O/S FENDER .		500.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	30.00
			2,020.00	1,150.00
<b>GRAND TOTAL</b>			<b>3,207.80</b>	<b>2,244.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,750.00</b>

Report Ref No. CC3/CTI21001230/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 8243S

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SMH 8243S**

**RE-INSPECTION**

