

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Jan-21

ESTIMATE REPAIR BILL FOR MAZDA 3 REGN NO: SMH 8243 S

1 pc	Rear o/s fender	\$	1,233.00	by ✓
1 pc	Rear windscreen moulding	\$	98.00	nr ✓
		\$	1,331.00	
		Less 20%	\$	266.20
			\$	1,064.80 ✓
S/NETT				
1 set	Rear n/s fender inner shield clips	\$	28.00	nn
1 pc	Sealant	\$	45.00	3000
	Sundry	\$	50.00	nn
	To dismantle and refit the rear windscreen	\$	120.00	✓
	To check Rear o/s wheel alignment	\$	80.00	Xnr 150
	To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heat on the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear bumper etc	\$	1,200.00	600.
	To putty and spray painting on Rear bumper, rear o/s fender	\$	500.00	400
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	30.
		\$	3,207.80	1030

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97445744
w/ 26/1/2R 5pm
d/p Resurvey before paint
Tanpin e/ha auto.wn
45 days

2244.80
4/56/750
03 days #